https://msdsreport.com/msds/BBDYR

LOW FUMING BRONZE

MSDS Number

BBDYR

National Stock Number

3439-00D001163

Product Name

LOW FUMING BRONZE

Manufacturer

J W HARRIS CO INC

Product Identification

Product ID:LOW FUMING BRONZE MSDS Date:01/01/1987 FSC:3439 NIIN:00D001163 MSDS Number: BBDYR

Responsible Party

J.W.HARRIS CO., INC.

Emergency Phone: (513)891-2000

Cage: 27911

Contractor

J. W. HARRIS CO., INC. CINCINNATI, OH 45242-4110 US

513-891-2000

Cage: 27911

Ingredients

COPPER (SARA III) CAS: 7440-50-8 RTECS: GL5325000 Fraction By Weight: 58% OSHA PEL0.1MG/M3 FUME/1 DUST ACGIH TLV: 0.2MG/M3 FUME; 9192 EPA Report Quantity: 5000 LBS DOT Report Quantity: 5000 LBS

ZINC (SARA III) CAS: 7440-66-6 RTECS: ZG8600000 Fraction By Weight: 39.7% OSHA PEL10 MG ZNO/M3 ACGIH TLV: 10 MG ZNO/M3; 9192 EPA Report Quantity: 1000 LBS DOT Report Quantity: 1000 LBS msds report

https://msdsreport.com/msds/BBDYR

•

TIN

CAS: 7440-31-5 RTECS: XP7320000 Fraction By Weight: 1% OSHA PEL2 MG/M3 ACGIH TLV: 2 MG/M3; 9192

MANGANESE (SARA III) CAS: 7439-96-5 RTECS: OO9275000 Fraction By Weight: 0.25% OSHA PEL(C) 5 MG/M3 DUST ACGIH TLV: 5 MG/M3 DUST 9293

IRON,CAS#7439-89-6,0.25-1.2%

CAS: 7439-89-6

RTECS: NO4565500

Fraction By Weight: 0.7%

ACGIH TLV: 5MG/CUM

Hazards

Effects of Overexposure:METALLIC TASTE,NAUSEA,TIGHTNESS OF CHEST,FEVER,DIZZINESS.EYE,NOSE,THROAT DRYNESS AND IRRITATION.

First Aid

First Aid:REMOVE FROM EXPOSURE AND OBTAIN PROMPT MEDICAL ATTENTION.IF UNCONSCIOUS,GIVE OXYGEN.IF NOT BREATHING GIVE CPR.EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY AMERICAN RED CROSS.

Fire Fighting

Extinguishing Media:EXTINGUISH WITH AGENT SUITABLE FOR SURROUNDING FIRE Unusual Fire/Explosion Hazard:WELDING ARC AND SPARKS CAN IGNITE COMBUSTIBLE PRODUCTS.

Accidental Release

Spill Release Procedures: CLEAN UP ANY GRINDING DUST OR WASTE RESIDUE AND PLACE IN SUITABLE DOT APPROVED DISPOSAL CONTAINER.

Handling

Other Precautions:TRAIN WELDER TO KEEP HIS HEAD OUT OF THE FUMES.MONITOR AIR TO ENSURE ACCEPTABLE EXPOSURES.AVOID ELECTRICAL SHOCK BY MAINTAINING DRY WORK AREA.

Exposure Controls

Respiratory Protection:FUME RESP.OR AIR SUPPLIED RESP.IN CONFINED SPACES. Ventilation:LOCAL EXHAUST TO MAINTN BELOW TLV. Protective Gloves:WELDER'S GLOVES Eye Protection:FACE SHLD W/FILTER LENS Other Protective Equipment:SUBST.DK.CLOTH,ARM PROTECTOR,APRON,HAT,SHOULDR.PROTECTION. Supplemental Safety and Health MSDS DATED NOV.85/OTHER INGRED:SILICON 0.04-0.15%/



Chemical Properties

HCC:N1

Appearance and Odor: COPPER BASED WELDING AND BRAZE WELDING WIRE & ROD.

Stability

Stability Indicator/Materials to Avoid:YES Hazardous Decomposition Products:FUMES OF METALS AND METAL OXIDES,CO,NO*2,O*3

Disposal

Waste Disposal Methods: DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.