

HOBART 13A

MSDS Number

BJYVQ

National Stock Number

3439-00-267-4787

Product Name

HOBART 13A

Manufacturer

HOBART BROTHERS CO

Product Identification

Product ID:HOBART 13A

MSDS Date:03/01/1990

FSC:3439

NIIN:00-267-4787

MSDS Number: BJYVQ

Responsible Party

HOBART BROTHERS CO

600 W MAIN ST HOBART SQUARE

TROY , OH 45373

US

Emergency Phone: 513-332-4000

Cage: 28835

Contractor

HOBART BROTHERS CO

TROY, OH 45373

US

513-339-6000

Cage: 28835

Ingredients

IRON

CAS: 7439-89-6

RTECS: NO4565500

Fraction By Weight: 70-90%

MANGANESE (SARA III)

CAS: 7439-96-5

RTECS: OO9275000

Fraction By Weight: 1-6%

OSHA PEL(C) 5 MG/M3 DUST

ACGIH TLV: 5 MG/M3 DUST 9293

TITANIUM DIOXIDE

CAS: 13463-67-7

RTECS: XR2275000

Fraction By Weight: 2-10%

OSHA PEL15 MG/M3 TDUST

ACGIH TLV: 10 MG/M3 TDUST; 9293

POTASSIUM SILICATE

CAS: 1312-76-1

Fraction By Weight:

SODIUM SILICATE

CAS: 1344-09-8

Fraction By Weight: 3-15%

Hazards

LD50 LC50 Mixture:UNCLASSIFIED WELDING FUMES=5MG/M3 PEL

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:SHORT TERM EXPOSURE TO WELDING FUMES, GASES OR DUST MAY RESULT IN DISCOMFORT SUCH AS DIZZINESS, NAUSEA, FEVER, DRYNESS AND/OR IRRITATION OF NOSE, THROAT AND EYES. SKIN SENSITIVITY MAY ALSO BE NOTED. A CUTE EXPOSURE FROM SOME TOXIC GASES MAYCAUSE PULMONARY EDEMA, ASPHYXIATION AND EXCESSIVE EXPOSURE CAN BE FATAL.

Explanation of Carcinogenicity:DOES NOT CONTAIN CARCINOGENIC METALLIC ELEMENTS.

Effects of Overexposure:EXPOSURE TO WELDING FUMES MAY RESULT IN DIZZINESS, NAUSEA, FEVER, DRYNESS AND/OR IRRITATION OF NOSE, THROAT AND EYES. SKIN SENSITIVITY MAY ALSO BE NOTED. WATERY EYES, HEADACHE, BREATHING DIFFICULTY, F REQUENT COUGHING AND/OR CHEST PAINS MAYOCCUR FROM ACUTE EXPOSURE. TOXIC GASES CAN BE FATAL.

Medical Cond Aggravated by Exposure:SOME WORKERS MAY BE AFFECTED BY A PRE-EXISTING CONDITIONS OF BREATHING PROBLEMS OR OTHER OCCUPATIONAL ILLNESS BECAUSE OF THE WIDE VARIATION IN INDIVIDUAL SUSCEPTIBILITIES.

First Aid

First Aid:IN CASE OF ELECTRICAL SHOCK, TURN OFF POWER PRIOR TO REMOVAL FROM EXPOSURE AREA AND ADMINISTRATION OF FIRST AID. REMOVE FROM EXPOSURE AREA AND CALL FOR MEDICAL AID; IF INHALED FUMES OF GASES AND BREAT HING IS DIFFICULT OR NOT BREATHING, BEGIN ARTIFICIAL RESPIRATION. IF NO DETECTABLE PULSE, BEGIN EXTERNAL HEART MASSAGE. EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY THE AMERICAN RED CROSS.

Fire Fighting

Flash Point:NONE

Extinguishing Media:USE SUITABLE MEDIA APPROPRIATE FOR SURROUNDING FIRES.

Fire Fighting Procedures:WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL FACED SELF CONTAINED BREATHING APPARATUS. COOL FIRE EXPOSED CONTAINERS WITH WATER SPRAY.

Accidental Release

Spill Release Procedures:CLEAN UP ANY GRINDING DUST OR WASTE RESIDUES AND PLACE IN SUITABLE DOT APPROVED CONTAINERS AND DISPOSE OF IN FULL COMPLIANCE WITH FEDERAL, STATE AND LOCAL REGULATIONS. AVOID INHALATION AND SKIN EXPOSURE.

Handling

Handling and Storage Precautions:WEAR GLOVES AND FLAME RETARDANT CLOTHING WHEN CUTTING, GRINDING OR WELDING. DO NOT EXPOSE SKIN TO RADIATION WHEN HOT CUTTING OR WELDING.

Other Precautions: PROVIDE PROTECTIVE SCREENS TO SHIELD OTHERS. WHEN ELECTRODES AND FLUXES ARE CONSUMED, THE FUME AND GAS DECOMPOSITION PRODUCTS GENERATED ARE DIFFERENT IN FORM FROM THE INGREDIENTS LISTED. NEW COMPOUNDS NOT IN THE ELECTRODES MAY FORM.

Exposure Controls

Respiratory Protection: USE WELD FUME RESPIRATOR OR AIR SUPPLIED RESPIRATOR WHEN ARC CUTTING, OR WELDING IN A CONFINED SPACE OR WHERE LOCAL EXHAUST OR GENERAL VENTILATION DOES NOT KEEP EXPOSURE BELOW RECOMMENDED LIMITS. USE ONLY NIOSH APPROVED RESPIRATORS.
Ventilation: USE ENOUGH VENTILATION WHEN WELDING TO KEEP THE DUST, FUMES & GASES FROM THE WORKERS BREATHING ZONE
Protective Gloves: WELDERS LEATHER GLOVES
Eye Protection: OSHA APPROVED GOGGLES/FACE SHIELD W/LENS
Other Protective Equipment: FLAME RETARDANT CLOTHING WHEN CUTTING, GRINDING OR WELDING. DO NOT EXPOSE SKIN TO RADIATION WHEN HOT CUTTING OR WELDING.
Work Hygienic Practices: WASH THOROUGHLY BEFORE EATING OR SMOKING. LAUNDRER CONTAMINATED CLOTHING BEFORE REUSE.
Supplemental Safety and Health
WELDING AND HOT CUTTING FUMES & GASES CANNOT BE CLASSIFIED SIMPLY. THEIR COMPOSITION AND QUANTITY ARE DEPENDENT ON THE METAL BEING WELDED, THE PROCEDURES, PROCESSES AND THE TYPE OF WIRE OR ELECTRODES USED. SPECIFICATION QQ-E-450 HAS BEEN CANCELLED. HOBART P/N 13A IS OBSOLETE AND REPLACED BY: 447A

Chemical Properties

HCC: N1
Boiling Pt: B.P. Text: NONE
Spec Gravity: >1
Appearance and Odor: WELDING ROD, 0.094 INCH ROUND

Stability

Stability Indicator/Materials to Avoid: YES
ACIDS/BASES
Hazardous Decomposition Products: WELDING/CUTTING OPERATION MAY PRODUCE OF OXIDES OF THE METALS SUCH AS MANGANESE, TITANIUM, IRON, POT/SODIUM AND SI, N₂, O₃

Disposal

Waste Disposal Methods: DISPOSE OF I/A/W FEDERAL, STATE & LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.