https://msdsreport.com/msds/BRTLC

ALLOY SHIELD NI1S

MSDS Number

BRTLC

National Stock Number

3439-00F028479

Product Name

ALLOY SHIELD NI1S

Manufacturer

ALLOY RODS CORP

Product Identification

Product ID:ALLOY SHIELD NI1S MSDS Date:01/11/1989 FSC:3439 NIIN:00F028479 MSDS Number: BRTLC

Responsible Party

ALLOY RODS CORP

1500 KAREN LN

HANOVER , PA 17331

US

Emergency Phone: 717-637-8911

Info Phone: 717-637-8911

Cage: GO230

Contractor

ESAB GROUP INC

517

HANOVER, PA 17331

US

717-637-8911 OR 800-933-7070

Cage: 84021

Ingredients

SILICON CAS: 7440-21-3 RTECS: VW0400000 OSHA PEL15 MG/M3 TDUST ACGIH TLV: 10 MG/M3 TDUST; 9293

NICKEL (SOLUBLE) (SUSPECTED HUMAN CARCINOGEN BY NTP, IARC, CAS: 7440-02-0 RTECS: QR5950000 OSHA PEL1 MG/CUM ACGIH TLV: 0.05 MG/CUM IC msds report

https://msdsreport.com/msds/BRTLC

•

IRON

CAS: 7439-89-6 RTECS: NO4565500 OSHA PEL10 MG/CUM ACGIH TLV: 5 MG/CUM

MANGANESE, MN COMPOUNDS

CAS: 7439-96-5

RTECS: 009275000

OSHA PEL(C) 5 MG/M3 DUST

ACGIH TLV: 5 MG/M3 DUST 9293

Hazards

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:NO Health Hazards Acute and Chronic:IRRITATION OF NOSE, THROAT, EYES. MAY LEAD TO SIDEROSIS WHICH MAY AFFECT PULMONARY FUNCTION. ACR RAYS CAN INJURE EYES & BURN SKIN. ELECTRIC SHOCK CAN KILL. SEE SUPP. Explanation of Carcinogenicity:SEE INGREDIENTS Effects of Overexposure:INHALATION: DIZZINESS, NAUSEA, IRRITATION OF NOSE & THROAT. EYES: IRRITATION. SKIN: DRYNESS & BURNS. Medical Cond Aggravated by Exposure:RESPIRATORY OR ALLERGIC CONDITIONS.

First Aid

First Aid: EMPLOY FIRST AID TECHNIQUES BY THE AMERICAN RED CROSS. OBTAIN MEDICAL ATTENTION IN ALL CASES.

Fire Fighting

Flash Point:NON-FLAMMABLE Unusual Fire/Explosion Hazard:WELDING ARC & SPARKS CAN IGNITE COMBUSTIBLES.

Handling

Handling and Storage Precautions: KEEP HEAD OUT OF THE FUMES. DON'T TOUCH LIVE ELECTRICAL PARTS. INSULATE FROM WORK & GROUND. Other Precautions: TO DETERMINE COMPOSITION & QUANTITY OF FUMES & GASES TO WHICH WORKERS ARE EXPOSED IS TO TAKE AN AIR SAMPLE INSIDE THE WELDERS HELMET OR IN THE WORKER'S BREATHING ZONE.

Exposure Controls

Respiratory Protection:USE RESPIRABLE FUME RESPIRATOR OR AIR SUPPLIED RESPIRATOR WHEN WELDING IN CONFINED SPACE OR WHERE LOCAL EXHAUST OR VENTILATION DOES NOT KEEP EXPOSURE BELOW TLV. Ventilation:LOCAL EXHAUST AT THE ARC TO KEEP THE FUMES & GASES BELOW THE TLV. Protective Gloves:WELDER'S GLOVES Eye Protection:FACE SHIELD W/APPROPRIATE FILTER LENS Other Protective Equipment:HELMET, ARM PROTECTORS, APRONS, HATS, SHOULDER PROTECTION, DARK SUBSTANTIAL CLOTHING, SCREENS, FLASH GOGGLES. Supplemental Safety and Health THE PRODUCT AS SUPPLIED IS NON-HAZARDOUS. HEALTH HAZARDS OCCUR DURING OPERATIONS. THE COMPOSITION & QUANTITY OF WELDING FUMES ARE DEPENDENT ON THE PROCESS, PROCEDURES, MEDIA, CONTAMINENTS IN THE ATMOS PHERE, & ELECTRODES USED.

Stability

Stability Indicator/Materials to Avoid:YES SEE SUPP Stability Condition to Avoid:SEE SUPP



Hazardous Decomposition Products:CO, CO2, OZONE & NITROGEN OXIDES FORMED BY THE RADIATION FROM ARC. WELDING FUMES - COMPLEX OXIDES FROM THE INGREDIENTS.

Disposal

Waste Disposal Methods: PREVENT FROM CONTAMINATING SURROUNDING ENVIRONMENT. DISCARD ANY PRODUCT RESIDUE, DISPOSABLE CONTAINER, OR LINER IN AN ENVIRONMENTALLY ACCEPTABLE MANNER, IN FULL COMPLIANCE W/FEDERAL, STATE & LOCAL REG ULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.