16-354,HEAVY DUTY RED TOOLMAKER'S INK

MSDS Number

BBCPF

National Stock Number

6850-00D000377

Product Name

16-354,HEAVY DUTY RED TOOLMAKER'S INK

Manufacturer

SEYMOUR OF SYCAMORE INC

Product Identification

Product ID:16-354,HEAVY DUTY RED TOOLMAKER'S INK
MSDS Date:01/01/1985
FSC:6850
NIIN:00D000377
MSDS Number: BBCPF

Responsible Party

SEYMOUR OF SYCAMORE,INC

917 CROSBY AVE

SYCAMORE , IL 60178-1343

US

Cage: 59581

Contractor

SEYMOUR OF SYCAMORE

SYCAMORE, IL 60178-1343

US

815-895-9101/800-255-3924

Cage: 59581

Ingredients

ETHYL ACETATE (SARA III)

CAS: 141-78-6

RTECS: AH5425000

Fraction By Weight: 1.66%

OSHA PEL400 PPM

ACGIH TLV: 400 PPM; 9192

EPA Report Quantity: 5000 LBS

DOT Report Quantity: 5000 LBS

2-ETHOXYETHYL ACETATE (CELLOSOLVE ACETATE) (EGEEA)

CAS: 111-15-9

RTECS: KK8225000

Fraction By Weight: 0.68%

OSHA PELS,100 PPM

ACGIH TLV: S, 5 PPM; 9192

N-BUTYL ACETATE (SARA III)

CAS: 123-86-4

RTECS: AF7350000

Fraction By Weight: 1.33%

OSHA PEL150 PPM/200 STEL

ACGIH TLV: 150 PPM/200STEL;9192

EPA Report Quantity: 5000 LBS

DOT Report Quantity: 5000 LBS

TOLUENE(TOLUOL),CAS# 108-88-3,SEE P/N IND D FOR REMAINING

Fraction By Weight: 4.47%

ACGIH TLV: 100 PPM

ISOPROPYL ACETATE

CAS: 108-21-4

RTECS: AI4930000

Fraction By Weight: 11.9%

OSHA PEL250 PPM/310 STEL

ACGIH TLV: 250 PPM/310STEL;9192

Hazards

Effects of Overexposure:INHALE-IRRITATS RESPIR TRACT,ACUTE CNS DEPRESS W HEADACH,DIZZ,CONFUS,UNCONS,COMA.IRRITATS EYES/SKIN

First Aid

First Aid:REMOVE TO FRESH AIR. GIVE CPR/OXYGEN IF NEED. SKIN:WASH WITH SOAP & WATER. EYES:FLUSH WITH WATER 15 MIN. KEEP WARM AND QUIET REMOVE CONTAMINATED CLOTHING.

Fire Fighting

Flash Point:N/A-SEE SUP DATA
Extinguishing Media:CO*2, FOAM, DRY CHEM.
Fire Fighting Procedures:WEAR SCBA,COOL EXPD CONTRS W H*20. H*20 INEFF ON FIRE.
Unusual Fire/Explosion Hazard:EXTREMELY FLAMMABLE CONTAINER MAY EXPLODE.VAPOR IS EXPLOS HAZARD.VAPOR MAY SPREAD AWAY FROM SPILL.

Accidental Release

Spill Release Procedures:REMOVE IGNITION SOURCES,VENTILATE AREA WELL.ABSORB WITH VERMICULITE OR OTHER MATERIALS, SUCH AS SAWDUST,RAGS,PAPER & PLACE IN CLOSED CONTAINER. USE NON SPARKING TOOLS. WEAR PROPER PROTECTIVE EQUIPMENT DURING CLEAN UP.

Handling

Handling and Storage Precautions:STORE IN COOL,DRY,WELL VENT,LOW FIRE RISK AREA. PROTECT CONTRS FROM PHYS DAMAGE.KEEP OUT OF DIR RAYS OF SUN AWAY FR ORG PROD & OTHER EASILY OXID MATL
Other Precautions:DO NOT STORE ABOVE 120F.

Exposure Controls

Respiratory Protection:AVOID CONTINUOUS BRTHNG OF VAPORS,WEAR SCBA IN FIRE;APPRVD RESPIR.
Ventilation:MECH(GEN)OR LOCAL EXHAUST THAT PROVIDES ADEQUATE

VENTILATION
Protective Gloves:IMPERVIOUS
Eye Protection:GOGGLES/FACE SHIELD
Other Protective Equipment:FULL WORK CLOTHING TO PREVENT REPEATED OR PROLONGED CONTACT.
Supplemental Safety and Health
FP OF LIQUID IN AEROSOL CON -10F/-23C.2 FORMULATIONS FOUND FOR THIS NSN WITH 4 PARTS.A & B FOR PRODUCT 16-358;C & D FOR PRODUCT 16-354.KEY1

Chemical Properties

HCC:V3
Vapor Pres:UNK
Vapor Density:>1
Spec Gravity:UNK
Evaporation Rate & Reference:>1(ETHER=1)
Appearance and Odor:AEROSOL PAINT(40 PSI AT 70F.
Percent Volatiles by Volume:85

Stability

Stability Indicator/Materials to Avoid:YES
STRONG OXIDIZING AGENTS.
Stability Condition to Avoid:HEAT, IGNITION SOURCES
Hazardous Decomposition Products:TOXIC FUMES,FLAMMABLE GASES, IRRITATING GASES

Disposal

Waste Disposal Methods:KEEP IN COVERED DRUMS,PENDING DISPOSAL. HANDLE & DISPOSE IN FULL COMPLIANCE WITH ALL APPLICABLE INTERNATIONAL,FEDERAL,STATE, & LOCAL REGULATIONS. DO NOT INCINERATE AEROSOL.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.