ITEM 41

MSDS Number

BBGLF

National Stock Number

6850-00F000352

Product Name

ITEM 41

Manufacturer

WESTERN CHEMICAL COMPANY

Product Identification

Product ID:ITEM 41
MSDS Date:01/01/1985
FSC:6850
NIIN:00F000352
MSDS Number: BBGLF

Responsible Party

WESTERN CHEMICAL COMPANY

Emergency Phone: 816/842-0560

Cage: 08824

Contractor

WESTERN WATER MANAGEMENT/WESTERN CHEMICAL CO

NORTH KANSAS CITY, MO 64116-4414

US

816-842-0560

Cage: 08824

Ingredients

MANUFACTURER STATES PRODUCT DOES NOT CONTAIN HAZARDOUS

Hazards

Effects of Overexposure:CAN IRRITATE SKIN AND EYES ON CONTACT. HARMFUL IF SWALLOWED. INHALATION OF DUST HARMFUL.

First Aid

First Aid:FOR SKIN AND/OR CONTACT: FLUSH THE AFFECTED AREA WITH LOTS OF WATER FOR AT LEAST 15 MINUTES. FOR EYE CONTACT CONSULT A PHYSICIAN. INGESTION: HAVE CONSCIOUS VICTIM DRINK LOTS OF WATER AND INDUCE VOMITI NG. SEE A PHYSICIAN.

Fire Fighting

Extinguishing Media:CO2
Fire Fighting Procedures:WEAR PROTECTIVE CLOTHING, SELF-CONTAINED BREATHING APPARATUS
Unusual Fire/Explosion Hazard:CAN STIMULATE COMBUSTION OF ORGANIC MATTER. THERMAL DECOMP CAN GENERATE TOXIC NITROGEN OXIDES.

Accidental Release

Spill Release Procedures:WEAR PROTECTIVE CLOTHING. AVOID BREATHING DUST. SWEEP UP SPILLS. RESIDUE MAY USUALLYE FLUSHED DOWN DRAIN.

Handling

Handling and Storage Precautions:STORE AWAY FROM ACIDS AND OXIDIZABLE

MATERIALS. STORE IN A COOL, DRY AREA AWAY FROM FLAMES OR ARKS.
AVOID BREATHING DUST.
Other Precautions:AVOID CONTACT WITH SKIN AND EYES. WASH CONTAMINATED CLOTHING BEFORE REUSE.

Exposure Controls

Respiratory Protection:NIOSH APPROVED DUST MASK
Ventilation:MECHANICAL AS REQUIRED TO ELIMINATE DUST
Protective Gloves:RUBBER
Eye Protection:CHEMICAL GOGGLES
Other Protective Equipment:EMERGENCY SHOWER AND EYE WASH STATIONS
Supplemental Safety and Health
1345 TANEY, NORTH KANSAS CITY, MO 64116.

Chemical Properties

Solubility in Water:COMPLETE
Appearance and Odor:CREAM COLORED POWDER WITH FAINT ODOR.

Stability

Stability Indicator/Materials to Avoid:YES
ACIDIC MATERIALS AND ORGANICS
Stability Condition to Avoid:HIGH TEMPERATURES, OPEN FLAMES, ACIDIC MATERIALS, COMBUSTBLS
Hazardous Decomposition Products:OXIDES OF NITROGEN FUMES.

Disposal

Waste Disposal Methods:CONSULT FEDERAL, STATE AND LOCAL AUTHORITIES FOR APPROVED DISPOSAL PROCEDURES.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.