



PRESTONE (R) HEAVY DUTY STOP LEAK

MSDS Number

BBBXY

National Stock Number

6850-00B210002

Product Name

PRESTONE (R) HEAVY DUTY STOP LEAK

Manufacturer

UNION CARBIDE

Product Identification

Product ID:PRESTONE (R) HEAVY DUTY STOP LEAK

MSDS Date:11/15/1985

FSC:6850

NIIN:00B210002

MSDS Number: BBBXY

Responsible Party

UNION CARBIDE

DANBURY , CT 06817

US

Emergency Phone: 1-800-UCC-HELP

Cage: 07098

Contractor

UNION CARBIDE

EAST HARTFORD, CT 06108

US

800-822-4357

Cage: 07098

Ingredients

METALLIC SILICATES

ORGANIC FIBERS (TRADE SECRET)

Hazards

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES

Health Hazards Acute and Chronic:THIS PRODUCT CONTAINS DIAMTOMACEOUS SILICA,THE POSSIBILITY OF CHRONIC EFFECTS ON THE LUNGS MUST BE CONSIDERED IF LONG-TERM OVEREXPOSURE TO DUST OCCURS.

Effects of Overexposure:SAME AS HEALTH HAZARDS ACUTE AND CHRONIC.

Medical Cond Aggravated by Exposure:PHYSICAL AND CHEMICAL PROPERTIES OF THIS MATERIAL SUGGEST THAT OVEREXPOSURE IS UNLIKELY TO AGGRAVATE EXISTING MEDICAL CONDITIONS.

First Aid

First Aid:SWALLOWING:NO EMERGENCY CARE ANTICIPATED.SKIN:REMOVE CONTAMINATED CLOTHING AND WASH SKIN WITH SOAP AND WATER.INHALATION:REMOVE TO FRESH AIR.EYES:FLUSH EYES THOROUGHLY WITH PLENTY OF WATER.SEEK MEDICAL ATTENTION IF DISCOMFORT PERSISTS.

Fire Fighting



Extinguishing Media:WATER FOG,FOAM,ALCOHOL FOAM,CO2 AND DRY CHEMICAL.
Fire Fighting Procedures:NONE
Unusual Fire/Explosion Hazard:NONE EXPECTED

Accidental Release

Spill Release Procedures:WEAR SUITABLE PERSONAL PROTECTIVE EQUIPMENT.COLLECT MATERIAL FOR DISPOSAL.LARGER SPILLS MAY BE ABSORBED ON VERMICULITE OR OTHER SIMILAR MATERIAL.

Exposure Controls

Respiratory Protection:NONE REQUIRED FOR NORMAL USE.FOR BULK SPILL CLEAN-UP AND OTHER OPERATIONS WHICH MAY RESULT IN EMPLOYEE EXPOSURE ABOVE THE PEL,USE NIOSH/MSHA APPROVED RESPIRATOR FOR TOXIC DUST.
Ventilation:LOCAL EXHAUST VENTILATION IS REQUIRED FOR OPERATIONS WHERE EXPOSURE TO EMPLOYEES EXCEEDS THE PEL.
Protective Gloves:FOLLOW PLANT SAFETY PRACTICE.
Eye Protection:FOLLOW PLANT SAFETY PRACTICE.
Supplemental Safety and Health
AVOID PROLONGED INHALATION OF VAPOR OR MIST.AVOID EYE AND SKIN CONTACT.

Chemical Properties

Boiling Pt:B.P. Text:760 MM HG,F
Vapor Pres:MM HG,68F
Vapor Density:AIR=1
Evaporation Rate & Reference:BUTYL ACETATE=1
Solubility in Water:NOT SOLUBLE
Appearance and Odor:SLIGHT MUSTY ODOR.LIGHT TAN GRANULAR APPEARANCE.
Percent Volatiles by Volume:0

Stability

Stability Indicator/Materials to Avoid:YES
NONE
Hazardous Decomposition Products:MAY GIVE OFF CARBON MONOXIDE IF BURNED WITH INSUFFICIENT AIR.

Disposal

Waste Disposal Methods:INCINERATE OR LANDFILL IN ACCORDANCE WITH FEDERAL,STATE AND LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.