

TRUST-X TAPE

MSDS Number

BBDVT

National Stock Number

3439-00D001093

Product Name

TRUST-X TAPE

Manufacturer

X ERGON A PARTSMaster CO DIV OF NCH

Product Identification

Product ID:TRUST-X TAPE

MSDS Date:01/01/1987

FSC:3439

NIIN:00D001093

MSDS Number: BBDVT

Responsible Party

X-ERGON,A PARTSMaster CO.,DIV OF NCH

Emergency Phone: (214)438-4144X013

Cage: EO081

Contractor

X-ERGON,A PARTSMaster CO.,DIV OF NCH

152170

IRVING, TX 75015

US

972-438-1381

Cage: EO081

Ingredients

NICKEL (SARA III)

CAS: 7440-02-0

RTECS: QR5950000

OSHA PEL1 MG/M3

ACGIH TLV: 1 MG/M3; 9192

ALUMINUM (SARA III)

CAS: 7429-90-5

RTECS: BD0330000

OSHA PEL15MG/M3 DUST/5 FUME

ACGIH TLV: 10MG/M3 DUST; 9192

MOLYBDENUM

CAS: 7439-98-7

RTECS: QA4680000

OSHA PEL15 MG/M3 TDUST

ACGIH TLV: 10 MG/M3; 9293

Hazards

Effects of Overexposure: METALLIC TASTE, NAUSEA TIGHTNESS OF CHEST, FEVER, DIZZINESS EYE, NOSE, THROAT DRYNESS AND IRRITATION.

First Aid

First Aid: REMOVE FROM EXPOSURE AND OBTAIN PROMPT MEDICAL ATTENTION. IF UNCONSCIOUS, GIVE OXYGEN. IF NOT BREATHING GIVE CPR. EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY AMERICAN RED CROSS- IF INGESTED, DO NOT INDUCE VOMIT. SEE A DOCTOR.

Fire Fighting

Extinguishing Media: EXTINGUISH WITH AGENT SUITABLE FOR SURROUNDING FIRE
Unusual Fire/Explosion Hazard: WELDING ARC AND SPARKS CAN IGNITE COMBUSTIBLE PRODUCTS

Accidental Release

Spill Release Procedures: CLEAN UP ANY GRINDING DUST OR WASTE RESIDUE AND PLACE IN SUITABLE DOT APPROVED DISPOSAL CONTAINER

Handling

Other Precautions: TRAIN WELDER TO KEEP HIS HEAD OUT OF THE FUMES. MONITOR AIR TO ENSURE ACCEPTABLE EXPOSURES. AVOID ELECTRICAL SHOCK BY MAINTAINING DRY WORK AREA.

Exposure Controls

Respiratory Protection: FUME RESP. OR AIR SUPPLIED RESP. IN CONFINED SPACES.

Ventilation: LOCAL EXHAUST TO MAINTAIN BELOW TLV.

Protective Gloves: WELDER'S GLOVES

Eye Protection: FACE SHLD W/FILTER LENS.

Other Protective Equipment: SUBST. DK. CLOTH, ARM PROTECTOR, APRON, HAT, SHOULDR. PROTECTION.

Supplemental Safety and Health

MSDS DATED 03-24-86/

Chemical Properties

HCC: N1

Stability

Stability Indicator/Materials to Avoid: YES

Hazardous Decomposition Products: FUMES OF METALS AND METAL OXIDES, CO, NO₂, O₃

Disposal

Waste Disposal Methods: DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.