

CORE-BRAZE BRAZ ROD 3/32

MSDS Number

BBDVV

National Stock Number

3439-00D001094

Product Name

CORE-BRAZE BRAZ ROD 3/32

Manufacturer

X ERGON A PARTSMaster CO DIV OF NCH

Product Identification

Product ID: CORE-BRAZE BRAZ ROD 3/32

MSDS Date: 01/01/1987

FSC: 3439

NIIN: 00D001094

MSDS Number: BBDVV

Responsible Party

X-ERGON, A PARTSMaster CO., DIV. OF NCH

Emergency Phone: (214)438-4144X013

Cage: EO081

Contractor

X-ERGON, A PARTSMaster CO., DIV OF NCH

152170

IRVING, TX 75015

US

972-438-1381

Cage: EO081

Ingredients

ZINC (SARA III)

CAS: 7440-66-6

RTECS: ZG8600000

OSHA PEL10 MG ZNO/M3

ACGIH TLV: 10 MG ZNO/M3; 9192

EPA Report Quantity: 1000 LBS

DOT Report Quantity: 1000 LBS

SODIUM TETRABORATE, DECAHYDRATE

CAS: 1303-96-4

RTECS: VZ2275000

OSHA PEL10 MG/M3

ACGIH TLV: 5 MG/M3; 9192

BORIC ACID, CAS#10043-35-3

CAS: 10043-35-3

RTECS: ED4550000

COPPER (SARA III)

CAS: 7440-50-8

RTECS: GL5325000

OSHA PEL0.1MG/M3 FUME/1 DUST

ACGIH TLV: 0.2MG/M3 FUME; 9192

EPA Report Quantity: 5000 LBS

DOT Report Quantity: 5000 LBS

TIN

CAS: 7440-31-5

RTECS: XP7320000

OSHA PEL2 MG/M3

ACGIH TLV: 2 MG/M3; 9192

Hazards

Effects of Overexposure:METALLIC TASTE,NAUSEA, TIGHTNESS OF CHEST,FEVER,DIZZINESS.EYE,NOSE,THROAT DRYNESS AND IRRITATION

First Aid

First Aid:REMOVE FROM EXPOSURE AND OBTAIN PROMPT MEDICAL ATTENTION.IF UNCONSCIOUS,GIVE OXYGEN.IF NOT BREATHING GIVE CPR.EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY AMERICAN RED CROSS.

Fire Fighting

Extinguishing Media:EXTINGUISH WITH AGENT SUITABLE FOR SURROUNDING FIRE
Unusual Fire/Explosion Hazard:WELDING ARC AND SPARKS CAN IGNITE COMBUSTIBLE PRODUCTS.

Accidental Release

Spill Release Procedures:CLEAN UP ANY GRINDING DUST OR WASTE RESIDUE AND PLACE IN SUITABLE DOT APPROVED DISPOSAL CONTAINER.

Handling

Other Precautions:TRAIN WELDER TO KEEP HIS HEAD OUT OF THE FUMES.MONITOR AIR TO ENSURE ACCEPTABLE EXPOSURES.AVOID ELECTRICAL SHOCK BY MAINTAINING DRY WORK AREA.

Exposure Controls

Respiratory Protection:FUME RESP.OR AIR SUPPLIED RESP.IN CONFINED SPACES.

Ventilation:LOCAL EXHAUST TO MAINTN BELOW TLV.

Protective Gloves:WELDER'S GLOVES

Eye Protection:FACE SHLD W/FILTER LENS.

Other Protective Equipment:SUBST.DK.CLOTH,ARM

PROTECTOR,APRON,HAT,SHOULDR.PROTECTION.

Supplemental Safety and Health

MSDS DATED 03-21-86/

Chemical Properties

HCC:N1

Appearance and Odor:3/32 INCH DIA. CORE-BRAZE BRAZ ROD

Stability

Stability Indicator/Materials to Avoid:YES

Hazardous Decomposition Products:FUMES OF METALS AND METAL

OXIDES,CO,NO*2,O*3.

Disposal

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL,STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.