
CUPRO NICKEL 70/30 CDA ALLOY 715

MSDS Number

BBNPM

National Stock Number

3439-00F003703

Product Name

CUPRO NICKEL 70/30 CDA ALLOY 715

Manufacturer

HUSSEY COPPER LTD

Product Identification

Product ID:CUPRO NICKEL 70/30 CDA ALLOY 715

MSDS Date:01/01/1987

FSC:3439

NIIN:00F003703

MSDS Number: BBNPM

Responsible Party

HUSSEY COPPER LTD/LEETSDALE, PA 15056

Emergency Phone: (421) 857-4200

Cage: EO736

Contractor

HUSSEY COPPER LTD/LEETSDALE, PA 15056

LEETSDALE, PA 15056

US

412-857-4200

Cage: EO736

Ingredients

COPPER (SARA III)

CAS: 7440-50-8

RTECS: GL5325000

Fraction By Weight: 86.5%

OSHA PEL0.1MG/M3 FUME/1 DUST

ACGIH TLV: 0.2MG/M3 FUME; 9192

EPA Report Quantity: 5000 LBS

DOT Report Quantity: 5000 LBS

NICKEL (SARA III)

CAS: 7440-02-0

RTECS: QR5950000

Fraction By Weight: 11.0%

OSHA PEL1 MG/M3

ACGIH TLV: 1 MG/M3; 9192

IRON

RTECS: NO6975000

Fraction By Weight: 1.75%

ACGIH TLV: 5MG/CUM

MANGANESE (SARA III)

CAS: 7439-96-5

RTECS: OO9275000

Fraction By Weight: .75%

OSHA PEL(C) 5 MG/M3 DUST

ACGIH TLV: 5 MG/M3 DUST 9293

Hazards

Effects of Overexposure:GINGIVITIS, STOMATITIS METALLIC TASTE, SNEEZING, CONGESTION, NAUSEA, CHILLS, FEVER.

First Aid

First Aid:SKIN: FLUSH THOROUGHLY WITH WATER. EYES: FLUSH WITH WATER, CALL PHYSICIAN. INGESTION: CALL PHYSICIAN. INHALATION: REMOVE VICTIM TO FRESH AIR, CALL PHYSICIAN.

Accidental Release

Spill Release Procedures:WEAR RESPIRATOR FOLLOW OSHA USE INSTRUCTIONS, SHOVEL UP OR VACUUM AND PLACE IN APPROD DOT CONTAINER AND SEAL. WASH CONTAMINATED CLOTHING.

Handling

Handling and Storage Precautions:AVOID BREATHING DUST OR FUMES. DON'T TAKE INTERNALLY.

Other Precautions:PRECLUDE FROM EXPOSURE TO FUME AND DUST THOSE INDIVIDUALS WITH DISEASES OF THE SKIN, SINUSES AND LUNGS.

Exposure Controls

Respiratory Protection:NIOSH/MSHA APPROVED DUST/FUME RESPIRATOR

Ventilation:LOCAL EXHAUST: DUST/FUME: IF TLV VALUES EXCEEDED

Eye Protection:GOGGLES

Supplemental Safety and Health

MELTING POINT: 2010F

Chemical Properties

Boiling Pt:B.P. Text:2010F

Spec Gravity:8.94

Solubility in Water:NEGLIGIBLE

Stability

Stability Indicator/Materials to Avoid:YES

(DUST & FUME) ACETYLENE, CHLORINE

Hazardous Decomposition Products:COPPER FUME

Disposal

Waste Disposal Methods:DISPOSE OF CONTAMINATED PRODUCT AND MATERIALS USED IN CLEANING UP SPILLS OR LEAKS IN A MANNER APPROVED FOR THIS MATERIAL. FOLLOW FEDERAL, STATE AND LOCAL REGULATIONS FOR DISPOSAL.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their

particular situation.