

## **CORLOY 1CRMO, 2CRMO, T-1, AWS A5.28**

### **MSDS Number**

BBXSP

### **National Stock Number**

3439-00F007327

### **Product Name**

CORLOY 1CRMO, 2CRMO, T-1, AWS A5.28

### **Manufacturer**

HOBART BROTHERS CO

### **Product Identification**

Product ID: CORLOY 1CRMO, 2CRMO, T-1, AWS A5.28

MSDS Date: 01/01/1987

FSC: 3439

NIIN: 00F007327

MSDS Number: BBXSP

### **Responsible Party**

HOBART BROTHERS CO/TROY, OH 45373

Emergency Phone: (513) 339-6000

Cage: 28835

### **Contractor**

HOBART BROTHERS CO

TROY, OH 45373

US

513-339-6000

Cage: 28835

### **Ingredients**

SILICON

RTECS: EW0400000

ACGIH TLV: 20 MG/CUM

COPPER (SARA III)

CAS: 7440-50-8

RTECS: GL5325000

OSHA PEL 0.1MG/M3 FUME/1 DUST

ACGIH TLV: 0.2MG/M3 FUME; 9192

EPA Report Quantity: 5000 LBS

DOT Report Quantity: 5000 LBS

NICKEL (SEE SUPPLEMENTAL FOR INGREDIENTS)

RTECS: AR5950000

ACGIH TLV: 1 MG/CUM

CHROMIUM (SARA III)

CAS: 7440-47-3

RTECS: GB4200000

OSHA PEL1 MG/M3

ACGIH TLV: 0.5 MG/M3; 9192

EPA Report Quantity: 1 LB

DOT Report Quantity: 1 LB

TITANIUM DIOXIDE

CAS: 13463-67-7

RTECS: XR2275000

OSHA PEL15 MG/M3 TDUST

ACGIH TLV: 10 MG/M3 TDUST; 9293

## Hazards

Effects of Overexposure:DIZZINESS, NAUSEA, DRYNESS, IRRITATION OF NOSE, THROAT, EYES, DAMAGE TO LUNGS & ASTHAMA, KIDNEYS.

## First Aid

First Aid:EYE & SKIN: IF IRRITATION OR FLASH BURNS DEVELOP AFTER EXPOSURE, CONSULT PHYSICIAN.

## Fire Fighting

Flash Point:NON-FLAMMABLE

Unusual Fire/Explosion Hazard:WELDING ARC & SPARKS CAN IGNITE COMBUSTIBLES.

## Handling

Handling and Storage Precautions:ARC RAYS CAN INJURE EYE & BURN SKIN. ELECTRIC SHOCK CAN KILL. TRAIN THE WELDER TO KEEP HIS HEAD OUT OF THE FUMES.

Other Precautions:TO DETERMINE THE COMPOSITION/QTY OF FUMES & GASES TAKE AN AIR SAMPLE INSIDE THE WELDER'S HELMET OR IN BREATHING OZONE.

## Exposure Controls

Respiratory Protection:USE NIOSH APPROVED AIR SUPPLIED RESPIRATOR WHEN WELDING IN CONFINED

Ventilation:USE LOCAL EXHAUST VENTILATION TO KEEP TLV

Protective Gloves:WELDER'S

Eye Protection:FACESHIELD W/FILTER LENS

Other Protective Equipment:ARM PROTECTORS, APRONS, HATS, SHOULDER PROTECTION.

Supplemental Safety and Health

MSDS DATE: 8/85. ALSO CONTAINS: IRON, MANGANESE, MOLYBDENUM.

## Stability

Stability Indicator/Materials to Avoid:YES

FE, MN, SI, TI, CR, NI, MO, CU, N

Hazardous Decomposition Products:CO, CO2, OZONE NOX. OXIDES OF FE/MN/SI/TI/CR/NI/MO/CU/N.

## Disposal

Waste Disposal Methods:PREVENT WASTE FROM CONTAMINATING SURROUNDING ENVIRONMENT. DISCARD ANY PRODUCT, RESIDUE, DISPOSABLE CONTAINER OR LINER IN AN ENVIRONMENTALLY ACCEPTABLE MANNER, IN FULL COMPLIANCE WITH FEDERAL, STATE & LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.