

AWS A5.29 FCAW FABSHIELD 3NI1

MSDS Number

BBXST

National Stock Number

3439-00F007331

Product Name

AWS A5.29 FCAW FABSHIELD 3NI1

Manufacturer

HOBART BROTHERS CO

Product Identification

Product ID:AWS A5.29 FCAW FABSHIELD 3NI1 MSDS Date:01/01/1987 FSC:3439 NIIN:00F007331

MSDS Number: BBXST

Responsible Party

HOBART BROTHERS CO/TROY, OH 45373

Emergency Phone: (513) 339-6000

Cage: 28835

Contractor

HOBART BROTHERS CO

TROY, OH 45373

US

513-339-6000 Cage: 28835

Ingredients

MAGNESIUM OXIDE

CAS: 1309-48-4 RTECS: OM3850000

OSHA PEL15 MG/M3 PARTICULATE ACGIH TLV: 10 MG/M3;TDUST; 9293

CALCIUM FLUORIDE

CAS: 7789-75-5 RTECS: EW1760000 OSHA PEL2.5 MG/M3 (F)

ACGIH TLV: 2.5 MG/M3 (F); 8990

BARIUM FLUORIDE

CAS: 7787-32-8 RTECS: CQ9100000 ACGIH TLV: 0.5 MG/CUM



ALUMINUM (SARA III)

CAS: 7429-90-5 RTECS: BD0330000

OSHA PEL15MG/M3 DUST/5 FUME ACGIH TLV: 10MG/M3 DUST; 9192

NICKEL (SARA III)
CAS: 7440-02-0
RTECS: QR5950000
OSHA PEL1 MG/M3

ACGIH TLV: 1 MG/M3; 9192

Hazards

Effects of Overexposure:DIZZINESS, NAUSEA, OR DRYNESS OR IRRITATION OF NOSE, THROAT OR EYES, SIDEROSIS.

First Aid

First Aid: EYE & SKIN: IF IRRITATION OF FLASH BURNS DEVELOP AFTER EXPOSURE, CONSULT PHYSICIAN.

Fire Fighting

Flash Point: NON FLAMMABLE Unusual Fire/Explosion Hazard: WELDING ARC & SPARKS CAN IGNITE COMBUSTIBLES.

Handling

Handling and Storage Precautions:TO DETERMINE THE COMPOSITION & QUANTITY OF FUMES/GASES TAKE AN AIR SAMPLE INSIDE THE WELDER'S LMET IF WORN OR IN THE WORKER'S BREATHING ZONE.

Other Precautions:ARC RAYS CAN INJURE EYES & BURN SKIN. ELECTRIC SHOCK CAN KILL.

Exposure Controls

Respiratory Protection: AIR SUPPLIED RESPIRATOR WHEN WELDING IN CONFINED SPACE IF >TLV.

Ventilation:LOCAL EXHAUST AT THE ARC TO KEEP THE FUMES/GASES Protective Gloves:WELDER'S

Eye Protection: FACE SHIELD W/FILTER LENS

Other Protective Equipment: ARM PROTECTORS, APRONS, HATS, SHOULDER

PROTECTION.

Supplemental Safety and Health

MSDS DATE: 8-85. ALSO CONTAINS: IRON (NO4565500), MANGANESE (OM2100000), TITANIUM OXIDE (XR2275000), SILICON (VW0400000).

Stability

Stability Indicator/Materials to Avoid:YES N/K _ Hazardous Decomposition Products:CO, CO2, OZONE, OXIDES OF FE/MN/SI/TI/MG/BA/AL/N/NI

Disposal

Waste Disposal Methods: PREVENT WASTE FROM CONTAMINATING SURROUNDING ENVIRONMENT. DISCARD ANY PRODUCT, RESIDUE, DISPOSABLE CONTAINER OR LINER IN AN ENVIRONMENTALLY ACCEPTABLE MANNER, IN FULL COMPLIANCE W/FEDERAL, STATE & LOC AL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever,



expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.