

ACETYLENE

MSDS Number

BHDHJ

National Stock Number

6830-00-286-5434

Product Name

ACETYLENE

Manufacturer

UNION CARBIDE CORP

Product Identification

Product ID:ACETYLENE
MSDS Date:04/01/1987
FSC:6830
NIIN:00-286-5434
MSDS Number: BHDHJ

Responsible Party

UNION CARBIDE CORPORATION

39 OLD RIDGEBURY ROAD

DANBURY , CT 06817-0001

US

Emergency Phone: 1-800-822-4357 CANADA 514-640-6400

Info Phone: ROUTINE INFO CONTACT LOCAL SUPPLIER

Cage: 36346

Contractor

UNION CARBIDE CORP LINDE DIV

DANBURY, CT 06817-0001

US

800-822-4357; 304-744-3487

Cage: 36346

Ingredients

ACETYLENE

CAS: 74-86-2

Fraction By Weight: 100%

ACGIH TLV: 750 PPM

Hazards

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Health Hazards Acute and Chronic:INGST;UNLIKELY RT BUT FRSTBITE OF LIPS/MOUTH MAY RESULT FROM CONTACT W/LIQ. IF LIQ IS INGST MAY CAUSE NAUSEA.SKIN:NO HRMFL EFFCTS EXPECTED FROM VAPOR.LIQ MAY CAUSE FRSTBITE.EYE:VAPOR/LIQ MAY CAUSE IRRITATION/FRSTBITE.INHL:ASPHYXIAN. MODTCONCNT OF VAPOR HDACHE,DROWINS,DIZZINS,NAUSEA,VOMITING,EXCS SALIVAT,& UNCONSCNS.
Effects of Overexposure:NONE CURRENTLY KNOWN.
Medical Cond Aggravated by Exposure:A NKOWLEDGE OF AVAILABLE TOXICOLOGY INFORMATION & PHYSICAL/CHEMICAL PROPERTIES OF MATERIAL SUGGEST THAT OVEREXPOSURE IS UNLIKELY TO AGGRAVATE EXISTNGMEDICAL CONDITIONS.

First Aid

First Aid:INGST: IF LIQUID IS SWALLOWED DONOT INDUCE VOMITING. CALL A PHYSICIAN. SKIN: FOREXPOSURE TO LIQUID, FLUSH W/WATER & WARM FROSTBITE AREA (NOT TO EXCEED 105F). INCASE OF MASSIVE EXPSR REMOVE CLTHNG W/SH OWERING W/WARM WTR. EYE: IMMEDIATELYFLUSH W/WTR FOR 15 MINUTES. SEEK AN OPHTHALMOLOGIST URGENTLY.INHL:REMOVE TO FRSH AIR. IF BREATHING STOPS,GIVE ARTIFCL RESP. OR OXYGEN IF BREATHING IS DIFFICULT.

Fire Fighting

Flash Point Method:TCC
Flash Point:OF/-17.8C
Autoignition Temp:Autoignition Temp Text:*****
Lower Limits:100
Upper Limits:2.3
Extinguishing Media:STOP FLW OF GAS W/O RISK WHILE CONT WTR SPRAY.ALLOW FIRE TO BRN OUT.ON SITE FIRE BRIGADES MUST COMPLY W/OSHA29CFR1910
Fire Fighting Procedures:EVACUATE ALL PERSONNEL FROM DANGER AREA. REMOVE ALL CONTNRS FROM AREA OF FIRE. ON SITE FIRE BRIGADES MUST COMPLY WITH OSHA 29 CFR1910.156.
Unusual Fire/Explosion Hazard:EXTRMLY FLAMBLE GAS. FORMS EXPLSV MIXT W/AIR & OXIDIZING AGENTS. CONTAINER MAY RUPTURE DUE TO HEAT OR FIRE. DO NOT EXTNGSH FLAMES DUE TO POSS. EXPLSV REIGNITN

Accidental Release

Spill Release Procedures:FORMS EXPLSV MIXTR W/AIR.IMMEDLY EVACUATE PERSNL FROM AREA.USE SCBA W/NEEDED.REMOVE ALL SOURCE OF IGNITION.REDUCE VAPORS W/FOG OR FINE WTR SPRAY. SHUT OFF LEAK IF W/O RISK.VENTL AREA OF LEAK OR MOVE LEAKING CONTAINER TO WELL VENTL AREA.

Handling

Handling and Storage Precautions:STORE IN COOL,DRY,WELL VENTL AREA. DONOT STORE NEAR OPEN FLAMES.DONOT GRND CYLNDR.DONOT STORE W/ OXYGEN/OXIDIZERS.PROTECT CYLND FROM PHYSCL DAMAGE
Other Precautions:DO NOT STRIKE ARC ON CYLINDER. HEAT/SPARKS DURING USE COULD BE SOURCE OF INGNTN.CLOSE VALVE WHEN NOT IN USE & WHEN EMPTY. NEVER WORK ON PRESSURIZED SYSTEMS. STORE CYLINDERS IN UPRIGHT POSITION SECU RED TO PREVENT FALLING OVER.

Exposure Controls

Respiratory Protection:USE RESPIRABLE FUME RESPIRATOR OR AIR SUPPLIED RESPIRATOR WHEN WORKING IN CONFINED SPACE OR WHERE LOCAL EXHAUST/VENTILATION DOES NOT KEEP EXPOSURE BELOW TLV. SELECT AS PER OSHA 29 CFR 1910.134
Ventilation:LOCAL EXHAUST OR BOTH, TO KEEP FUMES/GASES BELOW TLV'S IN WORKER'S BREATHING ZONE/THE GENERAL AREA.
Protective Gloves:WELDING GLOVES RECOMMENDED
Eye Protection:GOGGLES W/FILTER LENS/PROTECTION GOGGLES
Other Protective Equipment:AS NEEDED, WEAR HAND,HEAD & BODY PROTECTION WHICH HELPS TO PREVENT INJURY FROM RADIATION & SPARKS. SEE ANSI Z49.1
Supplemental Safety and Health
NK

Chemical Properties

Boiling Pt:B.P. Text:NA
Vapor Pres:635 PSIG
Vapor Density:0.91
Spec Gravity:NA
Evaporation Rate & Reference:NA
Solubility in Water:SLIGHT
Appearance and Odor:COLORLESS GAS AT NORMAL TEMPERATURE AND PRESSURE; GARLIC LIKE ODOR.
Percent Volatiles by Volume:100

Stability

Stability Indicator/Materials to Avoid:NO
COPPER, SILVER, MERCURY, OR THEIR ALLOYS, OXIDIZING AGENTS, ACIDS,
HALOGENS, MOISTURE.

Stability Condition to Avoid:STABLE AS SHIPPED. AVOID USE AT PRESSURE
ABOVE 15 PSIG

Hazardous Decomposition Products:THERMAL DECOMP OR BURNING MAY PRODC
CO/CO₂H₂.OTHER DECOMPSTNPROD OF NRML OPERT ORIGINATE FROM
VOLATILIZATION,OXIDATION.

Conditions to Avoid Polymerization:ELEVATED TEMPERATURE AND PRESSURE
AND/OR THE PRESENCE OF A CATALYST.

Disposal

Waste Disposal Methods:DISCARD ANY PRODUCT,RESIDUE,DISPOSABLE CONTAINER
OR LINER IN AN ENVIRONMENTALLY ACCEPTABLE MANNER IN COMPLIANCE
W/FEDERAL,STATE,& LOCAL REGULATIONS.PREVENT WASTE FROM
CONTAMINATING SURROUNDING AREA. KEEP PERSONNEL AWAY.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.