

PLASTER TRAP & ODOR NEUTRALIZER

MSDS Number

BJBWD

National Stock Number

6520-00F012184

Product Name

PLASTER TRAP & ODOR NEUTRALIZER

Manufacturer

HENRY SCHEIN INC

Product Identification

Product ID:PLASTER TRAP & ODOR NEUTRALIZER MSDS Date:08/01/1988 FSC:6520 NIIN:00F012184

NIIN:00F012184 MSDS Number: BJBWD

Responsible Party

HENRY SCHEIN INC.

5 HARBOR PARK DRIVE

PORT WASHINGTON , NY 11050

Emergency Phone: (516) 621-4300

Info Phone: (516) 621-4300

Cage: 64682

Contractor

HENRY SCHEIN INC

PORT WASHINGTON, NY 11050

(516) 621-4300 Cage: 64682

Ingredients

ISOPROPYL ALCOHOL (SARA III)

CAS: 67-63-0

RTECS: NT8050000

Fraction By Weight: 1-5% OSHA PEL400 PPM/500 STEL

0311A FEL400 FFM/300 31EE

ACGIH TLV: 400 PPM/500STEL;9192

Hazards

Routes of Entry: Inhalation:NO Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic: EYES: MAY CAUSE PAIN OR IRRITATION.

SKIN: MAY CAUSE SLIGHT IRRITATION. INGESTION: MAY CAUSE

GASTROINTESTINAL IRRITATION. Explanation of Carcinogenicity: NONE

Effects of Overexposure: EYES: MAY CAUSE PAIN OR IRRITATION. SKIN: MAY CAUSE SLIGHT IRRITATION. INGESTION: MAY CAUSE GASTROINTESTINAL IRRITATION.

11(1(1)(1)(1)(1)(1)

First Aid

First Aid: EYES: FLUSH W/WATER. CALL PHYSICIAN IF IRRITATION PERSISTS.



SKIN: FLUSH W/WATER. INGESTION: GIVE WATER OR MILK. CALL PHYSICIAN.

Fire Fighting

Flash Point: NONE

Extinguishing Media: WATER

Fire Fighting Procedures: NONE REQUIRED Unusual Fire/Explosion Hazard: NONE

Accidental Release

Spill Release Procedures: PROVIDE VENTILATION. WIPE OR MOP UP SPILLS. THEN RINSE W/WATER. FLOORS MAY BE SLIPPERY. USE CAUTION TO AVOID FALLS.

Handling

Handling and Storage Precautions:STORE IN A DRY, COOL AREA. KEEP OUT OF REACH OF CHILDREN. DON'T TAKE INTERNALLY. Other Precautions:READ ENTIRE LABEL BEFORE USING.

Exposure Controls

Respiratory Protection: NONE REQUIRED

Ventilation: NONE REQUIRED Protective Gloves: NONE REQUIRED Eye Protection: SAFETY GLASSES

Work Hygienic Practices: ALWAYS FOLLOW SAFE WORK PRACTICES.

Supplemental Safety and Health

Chemical Properties

Boiling Pt:B.P. Text:212F

Vapor Pres:18

Vapor Density:Spec Gravity:1.00

Evaporation Rate & Reference:(BU AC = 1): Solubility in Water:COMPLETE Appearance and Odor:CLEAR AMBER LIQUID; PLEASANTLY SCENTED

Stability

Stability Indicator/Materials to Avoid:YES

NONE

Stability Condition to Avoid: NONE

Hazardous Decomposition Products: OXIDES OF CARBON

Disposal

Waste Disposal Methods:TRIPLE RINSE CONTAINER THEN DISCARD IN TRASH.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.