

# FIBATAPE JOINT TAKE/FIBERGLASS MESH

#### **MSDS Number**

**BXJBM** 

#### **National Stock Number**

5640-00N058988

#### **Product Name**

FIBATAPE JOINT TAKE/FIBERGLASS MESH

#### Manufacturer

PERMA CLAS MESH INC

#### **Product Identification**

Product ID:FIBATAPE JOINT TAKE/FIBERGLASS MESH MSDS Date:03/02/1988 FSC:5640

NIIN:00N058988 MSDS Number: BXJBM

### **Responsible Party**

PERMA CLAS-MESH INC

179 W. BROADWAY

DOVER , OH 44622

US

Emergency Phone: 216-343-4441

Info Phone: 216-343-4441 Preparer: J P MACFADDEN

Cage: JO032

## Contractor

PERMA GLAS-MESH INC

DOVER, OH 44622

US

216-343-4441

Cage: 22116

## **Ingredients**

NON-HAZARDOUS INGREDIENTS

OSHA PELN/K ACGIH TLV: N/K

#### **Hazards**

LD50 LC50 Mixture: NONE SPECIFIED BY MANUFACTURER. Routes of Entry: Inhalation: NO Skin: NO Ingestion: NO Reports of Carcinogenicity: NTP: NO IARC: NO OSHA: NO

Health Hazards Acute and Chronic: LOOSE FIBERS CAN CAUSE SKIN IRRITATION

CHARACTERIZED BY ITCHING SKIN.

Explanation of Carcinogenicity:NOT RELEVANT Effects of Overexposure:SEE HEALTH HAZARDS. Medical Cond Aggravated by Exposure:DERMATITIS.

#### First Aid

First Aid:INGEST:CALL MD IMMEDIATELY . INHAL:REMOVE TO FRESH AIR. SUPPORT BREATHING (GIVE O\*2/ARTF RESP) . EYES:FLUSH WITH WATER FOR



AT LEAST 15 MINUTES. SKIN: WASH WITH SOAP AND WATER.

## **Fire Fighting**

Extinguishing Media:APPROPRIATE MEDIA FOR SURROUNDING FIRE. Fire Fighting Procedures:WEAR NIOSH/MSHA APPROVED SCBA & FULL PROTECTIVE EQUIPMENT.

Unusual Fire/Explosion Hazard: NONE SPECIFIED BY MANUFACTURER.

#### **Accidental Release**

Spill Release Procedures: SWEEP UP/PICK UP Neutralizing Agent: NONE SPECIFIED BY MANUFACTURER.

### Handling

Handling and Storage Precautions: STORE IN CLEAN, DRY AREA. Other Precautions: NONE KNOWN.

# **Exposure Controls**

Respiratory Protection: NIOSH/MSHA APPROVED DUST MASK WHEN REQUIRED.

Ventilation: LOCAL EXHAUST.

Protective Gloves: COTTON GLOVES.

Eye Protection: ANSI APPROVED CHEM WORKERS GOGGS .

Other Protective Equipment: LONG SLEEVE SHIRT.

Work Hygienic Practices: WASH HANDS AND ARMS W/SOAP AND WATER AFTER USE.

Supplemental Safety and Health NONE SPECIFIED BY MANUFACTURER.

### **Chemical Properties**

Spec Gravity:2.5 (H\*2O=1) Solubility in Water:INSOLUBLE

Appearance and Odor: COATED WOVEN GLAS-MESH TAPE-NO NOTICEABLE ODOR.

#### **Stability**

Stability Indicator/Materials to Avoid:YES NONE KNOWN Hazardous Decomposition Products:CO & CO\*2 GAS

### **Disposal**

Waste Disposal Methods:DRY GARBAGE AS PER LOCAL, STATE AND FEDERAL REGULATIONS .

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.