

177-11

MSDS Number

BBDHD

National Stock Number

6810-00D000763

Product Name

177-11

Manufacturer

HACH COMPANY

Product Identification

Product ID:177-11 MSDS Date:01/01/1987 FSC:6810 NIIN:00D000763 MSDS Number: BBDHD

Responsible Party

HACH COMPANY

100 DAYTON RD.

AMES, IA 50010-6402

US

Emergency Phone: 515-232-2533

Info Phone: 800-227-4224

Cage: 4T252

Contractor

HACH COMPANY

907

AMES, IA 50010

US

800-227-4224

Cage: 4T252

Ingredients

SODIUM AZIDE (SARA III)

CAS: 26628-22-8 RTECS: VY8050000

KILCS. V18030000

ACGIH TLV: C 0.11 PPM; 9192 EPA Report Quantity: 1000 LBS DOT Report Quantity: 1000 LBS

OSHA PELS, C 0.1 PPM(HN3)

SODIUM HYDROXIDE (SARA III)

CAS: 1310-73-2 RTECS: WB4900000 OSHA PEL2 MG/M3



ACGIH TLV: C 2 MG/M3; 9293 EPA Report Quantity: 1000 LBS DOT Report Quantity: 1000 LBS

Hazards

Effects of Overexposure: SKIN, EYE & THROAT BURNS.

First Aid

First Aid: WASH EYE IMMED W/PLENTY OF WATER FOR 15 MINUTES.GET MED ATTN. WASH SKIN W/SOAP&WATER. RMV CONTAMIN CLOTHNG&SOES. IF INGEST, RINSE MOUTH W/WATER. DO NOT INDCE VOMIT. GET IMMED MED ATTN.

Fire Fighting

Flash Point: NONE

Autoignition Temp:Autoignition Temp Text:NONE Extinguishing Media:SUITABLE FOR SURROUNDING FIRE Fire Fighting Procedures:WEAR SCBA & PROTECTIVE CLOTHING Unusual Fire/Explosion Hazard:NONE

Accidental Release

Spill Release Procedures: FLUSH W/LG AMT OF WATER, USING CARE NOT TO SPLATTER OR SPLASH THIS MATERIAL.

Handling

Handling and Storage Precautions: KEEP CONTAINER TIGHTLY CLOSED WHEN NOT IN USE. PROTECT FROM PHYSICAL DAMAGE.
Other Precautions: AVOID INGESTION AND CONTACT WITH SKIN, EYES& CLOTHING.

Exposure Controls

Respiratory Protection: NONE

Ventilation: MECHANICAL (GEN) RECOMMENDED

Protective Gloves: RUBBER Eye Protection: SAFETY GLASSES

Other Protective Equipment: APRON OR LAB COAT

Supplemental Safety and Health

MSDS NOT DATED. FOR DISSOLVED OXYGEN

Chemical Properties

HCC:B1

NRC/State Lic Num: NOT RELEVANT Solubility in Water: COMPLETE

Appearance and Odor: CLEAR, COLORLESS LIQUID.

Stability

Stability Indicator/Materials to Avoid:YES STRONG ACIDS.
Stability Condition to Avoid:NONE Hazardous Decomposition Products:NONE

Disposal

Waste Disposal Methods: DISPOSE BY NEUTRALIZATION I/A/W ALL LOCAL, STATE & FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.