



W.I.ASBESTOS GASKET CLOTH-TACKY

MSDS Number

BBDMK

National Stock Number

5330-00D000882

Product Name

W.I.ASBESTOS GASKET CLOTH-TACKY

Manufacturer

DARCO SOUTHERN INC

Product Identification

Product ID:W.I.ASBESTOS GASKET CLOTH-TACKY

MSDS Date:01/01/1987

FSC:5330

NIIN:00D000882

MSDS Number: BBDMK

Responsible Party

DARCO SOUTHERN, INC.

Emergency Phone: 703-773-2711

Cage: EO059

Contractor

DARCO SOUTHERN, INC.

454

INDEPENDENCE, VA 24348

US

703-773-2711

Cage: EO059

Ingredients

ASBESTOS, CHRYSOTILE

CAS: 12001-29-5

RTECS: CI6478500

Fraction By Weight: 40%

OSHA PEL0.2 FIBERS/CC

ACGIH TLV: 2 FIBERS/CC; A1;9192

COTTON (RAW)

RTECS: GN2275000

Fraction By Weight: 5%

OSHA PEL1MG/M3,SEE 1910.1043

ACGIH TLV: 0.2 MG/M3; DUST 9293

RUBBER, NATURAL (POLYISOPRENE), CAS 9006-04-6.

CAS: 9006-04-6

RTECS: VL8020000



Fraction By Weight: 50%

BRASS

Fraction By Weight: 5%.

Hazards

Effects of Overexposure:NONE

First Aid

First Aid:NONE

Fire Fighting

Flash Point:NONE

Extinguishing Media:WATER,FOAM,CO*2, DRY CHEMICAL

Fire Fighting Procedures:USE SCBA PP MODE

Unusual Fire/Explosion Hazard:HEAVY SMOKE PRODUCED WHEN LARGE AMT GASKET MATL IS BURNED.

Accidental Release

Spill Release Procedures:NONE

Handling

Handling and Storage Precautions:AVOID OXIDIZING MATERIALS. STORE IN CLEAN, DRY AREA.

Other Precautions:AVOID CREATION OF AIRBORNE FIBERS WHEN CUTTING. FOLLOW ALL OSHA HANDLING & USE REGULATIONS (29CFR 1910.1001)

Exposure Controls

Respiratory Protection:USE DUST MASK WHEN CUTTING MATL.

Ventilation:GENERAL MECHANICAL

Protective Gloves:NONE

Eye Protection:SAFETY GLASSES

Other Protective Equipment:NONE

Supplemental Safety and Health

MSDS NON-OSHA UNDATED RECD 21NOV86. TLV NOT APPLICABLE TO SHEET GASKET MATERIAL-SEE INGRED TLVS.

Chemical Properties

HCC:T6

Solubility in Water:NEG

Appearance and Odor:WHITE RUBBER COATED FABRIC, SLIGHT RUBBER ODOR

Percent Volatiles by Volume:0.

Stability

Stability Indicator/Materials to Avoid:YES

STRONG OXIDIZERS

Stability Condition to Avoid:DIRECT FLAME (WILL IGNITE RUBBER COATING)

Hazardous Decomposition Products:CARBON OXIDES

Disposal

Waste Disposal Methods:LANDFILL IAW ALL LAWS & REGS COVERING ASBESTOS WASTE DISPOSAL.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.