

HRH-327

MSDS Number

BBDSY

National Stock Number

9390-00D001047

Product Name

HRH-327

Manufacturer

HEXEL CORP

Product Identification

Product ID:HRH-327
MSDS Date:05/13/1986
FSC:9390
NIIN:00D001047
MSDS Number: BBDSY

Responsible Party

HEXEL CORPORATION
11711 DUBLIN BLVD
DUBLIN , CA 94568
US
Emergency Phone: 800-433-5072
Info Phone: 800-433-5072
Preparer: D. CROSS
Cage: EO076

Contractor

HEXEL CORPORATION
DUBLIN, CA 94568
US
800-433-5072
Cage: EO076

Ingredients

CARBON BLACK
CAS: 1333-86-4
RTECS: FF5800000
Fraction By Weight:
OSHA PEL3.5 MG/M3
ACGIH TLV: 3.5 MG/M3; 9394

SILICA, CRYSTALLINE - QUARTZ

CAS: 14808-60-7
RTECS: VV7330000
OSHA PEL10 MG/M3 RDUST; Z-3
ACGIH TLV: 0.1 MG/M3 RDUST;9394

Hazards

Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:ACUTE: INHALATION OF DUST MAY CAUSE MILD RESPIRATORY IRRITATION. CONTACT WITH DUST MAY CAUSE EYE IRRITATION. NO HEALTH EFFECTS NOTED FOR INGESTION. CHRONIC: PROLONGED OR REPEATED SKIN CONTACT MAY CAUSE IRRITATION.
Explanation of Carcinogenicity:NO INGREDIENT OF A CONCENTRATION OF 0.1% OR GREATER IS LISTED AS A CARCINOGEN OR SUSPECTED CARCINOGEN.
Effects of Overexposure:INHALED: COUGHING, SHORTNESS OF BREATH, SNEEZING, WHEEZING. EYES: REDNESS, DISCOMFORT. SKIN: REDNESS, DISCOMFORT. INGESTED: NONE NOTED.
Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

First Aid

First Aid:INHALED: REMOVE TO FRESH AIR. EYES: FLUSH WITH LOTS OF WATER FOR 15 MINUTES, HOLD LIDS OPEN. SEE DOCTOR IF SYMPTOMS PERSIST.
SKIN: WASH WITH SOAP AND WATER. INGESTED: NONE NOTED.

Fire Fighting

Flash Point:NONE
Extinguishing Media:CARBON DIOXIDE, WATER, DRY CHEMICAL, FOAM
Fire Fighting Procedures:WEAR SELF-CONTAINED BREATHING APPARATUS AND FULL PROTECTIVE CLOTHING SHOULD BE WORN IN ALL FIRES INVOLVING CHEMICALS.
Unusual Fire/Explosion Hazard:DUST GENERATED FROM MACHINING OPERATIONS WILL CONTAIN SMALL AMOUNTS OF CARBON BLACK WHICH MAY CREATE AN ELECTRICAL SHORT HAZARD.

Accidental Release

Spill Release Procedures:NONE SPECIFIED BY MANUFACTURER.
Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER.

Handling

Handling and Storage Precautions:NONE SPECIFIED BY MANUFACTURER.
Other Precautions:NONE SPECIFIED BY MANUFACTURER.

Exposure Controls

Respiratory Protection:NONE NORMALLY REQUIRED. IF ENGINEERING CONTROLS FAIL; USE NIOSH/MSHA APPROVED RESPIRATOR WITH DUST CARTRIDGE. USE IN ACCORDANCE WITH 29 CFR 1910.134.
Ventilation:USE LOCAL EXHAUST TO MAINTAIN EXPOSURE BELOW TLV/PEL.
Protective Gloves:WORK GLOVES
Eye Protection:SAFETY GLASSES
Other Protective Equipment:NONE SPECIFIED BY MANUFACTURER.
Work Hygienic Practices:WASH HANDS AFTER USE AND BEFORE EATING, DRINKING, OR SMOKING. LAUNDER CONTAMINATED CLOTHES BEFORE REUSE.
Supplemental Safety and Health
MSDS 1-15-86 MATERIAL POSES A HEALTH/SAFETY HAZARD WHEN A DUST PRODUCING OPERATION (SAWING,GRINDING)IS PERFORMED. RESPIRATORY PROTECTION IS NECESSARY FOR DUST PRODUCING OPERATIONS ONLY

Chemical Properties

HCC:N1
Solubility in Water:NEGLIGIBLE
Appearance and Odor:PHENOLIC RESIN RESIN/NOMEX HONEYCOMB
Percent Volatiles by Volume:0

Stability

Stability Indicator/Materials to Avoid:YES
NONE ANTICIPATED
Stability Condition to Avoid:NONE SPECIFIED BY MANUFACTURER.
Hazardous Decomposition Products:NO APPRECIABLE DECOMPOSITION BELOW 550F.

Disposal

Waste Disposal Methods:CONSULT WITH CERTIFIED WASTE DISPOSAL CONTRACTOR. DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.