

L-421 GREASE

MSDS Number

BBFFZ

National Stock Number

9150-00D001448

Product Name

L-421 GREASE

Manufacturer

WITCO CHEMICAL CORP KENDALL REFINING CO DIV

Product Identification

Product ID:L-421 GREASE

MSDS Date:11/14/1985

FSC:9150

NIIN:00D001448

MSDS Number: BBFFZ

Responsible Party

WITCO CHEMICAL CORP,KENDALL REFINING CO DIV

77 N. KENDALL AVE

BRADFORD , PA 16701-1726

US

Emergency Phone: 814-368-6111

Info Phone: 814-368-6111

Cage: 75273

Contractor

WITCO CHEMICAL CORP,KENDALL REFINING CO. DIVISION

2000

BRADFORD, PA 16701-1726

US

814-368-6111

Cage: 75273

Ingredients

PETROLEUM HYDROCARBON

LITHIUM STEARATE

CAS: 4485-12-5

RTECS: WI4370000

Hazards

Health Hazards Acute and Chronic:EXTENDED SKIN CONTACT MAY CAUSE DERMATITIS TO SOME INDIVIDUALS.

Effects of Overexposure:EXTENDED SKIN CONTACT MAY CAUSE DERMATITIS TO SOME INDIVIDUALS.

First Aid

First Aid:EYES-FLUSH W/WATER 15 MIN;CALL PHYSICIAN.SKIN-REMOVE EXCESS W/CLOTH OR PAPER. WASH THOROUGHLY W/SOAP & WATER. INHAL-REMOVE TO FRESH AIR & CALL DOC. INGEST-GET IMMED MED ATTN.

Fire Fighting

Flash Point Method:COG
Flash Point:>410F/210C
Extinguishing Media:DRY CHEMICAL,WATERFOG,CARBON DIOXIDE,FOAM,SAND/EARTH. DO NOT USE WATER EXCEPT AS FOG.
Fire Fighting Procedures:WATER MAY CAUSE FROTHING;EXPOSED MATL COULD BE COOLED W/WATER.

Accidental Release

Spill Release Procedures:TRANSFER BULK OF MIXTURE INTO ANOTHER CONTAINER. ABSORB RESIDUE W/INERT MATL LIKE EARTH OR SAND. SWEEP UP & DISPOSE OF.

Handling

Handling and Storage Precautions:DO NOT HANDLE OR STORE AT TEMPS OVER 100F/38C.

Exposure Controls

Respiratory Protection:NONE REQD.
Ventilation:NONE REQD.
Protective Gloves:RUBBER.
Eye Protection:CHEM SAFETY GOGGLES.
Other Protective Equipment:NONE
Supplemental Safety and Health

Chemical Properties

HCC:V6
Boiling Pt:B.P. Text:>500F/260C
Vapor Pres:NEG
Spec Gravity:0.9-0.95
Evaporation Rate & Reference:NEG
Solubility in Water:NEGLIGIBLE
Appearance and Odor:DARK AMBER,SEMI-SOLID GREASE,MINERAL OIL ODOR
Percent Volatiles by Volume:NEG

Stability

Stability Indicator/Materials to Avoid:YES
STRONG OXIDIZERS LIKE HYDROGEN PEROXIDE,BROMINE & CHROMIC ACID.
Hazardous Decomposition Products:FROM BURNING-CARBON MONOXIDE,CARBON DIOXIDE.

Disposal

Waste Disposal Methods:IAW ALL APPLICABLE FED,STATE & LOCAL REGS.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.