

ITEM 32

MSDS Number

BBGLD

National Stock Number

6850-00F000351

Product Name

ITEM 32

Manufacturer

WESTERN CHEMICAL COMPANY

Product Identification

Product ID:ITEM 32

MSDS Date:01/01/1985

FSC:6850

NIIN:00F000351

MSDS Number: BBGLD

Responsible Party

WESTERN CHEMICAL COMPANY

Emergency Phone: 816/842-0560

Cage: 08824

Contractor

WESTERN WATER MANAGEMENT/WESTERN CHEMICAL CO

NORTH KANSAS CITY, MO 64116-4414

US

816-842-0560

Cage: 08824

Ingredients

SODIUM BICHROMATE (SARA III)

CAS: 10588-01-9

RTECS: HX7700000

Fraction By Weight: 61%

OSHA PEL0.1 PPM CRO3;CEILING

ACGIH TLV: 0.05 MG CR/M3; 9192

EPA Report Quantity: 10 LBS

DOT Report Quantity: 10 LBS

Hazards

Effects of Overexposure:CHROMATE COMPOUNDS ARE SUSPECT CARCINOGENS.
CONTACT W/SKIN&EYES CAN CAUSE BURNS; POISONOUS IF SWAL

First Aid

First Aid:EYE AND/OR SKIN CONTACT: FLUSH THE AFFECTED AREA WITH WATER
FOR MINIMUM OF 15 MINUTES. HOLD EYELIDS OPEN IF NECESSARY. GET
EMERGENCY MEDICAL TREATMENT FOR EYE CONTACT. INGESTION: INDUCE
VOMITING. NEVE R FORCE FLUIDS IN UNCONSCIOUS PERSON, SEE MD.

Fire Fighting

Flash Point:NONE

Extinguishing Media:WATER

Fire Fighting Procedures:PROTECTIVE CLOTHING & SELF CONTAINED BREATHING APPARATUS
Unusual Fire/Explosion Hazard:NONE KNOWN.

Accidental Release

Spill Release Procedures:WEAR PROTECTIVE CLOTHING. AVOID CONTACT WITH SKIN AND EYES. SWEEP UP SPILLED MATERIA DO NOT FLUSH TO SEWERS.

Handling

Handling and Storage Precautions:AVOID CONTACT WITH EYES AND SKIN. AVOID BREATHING DUST. STORE IN DRY AREA. KEEP CONTAINER TIGHY CLOSED WHEN NOT IN USE.
Other Precautions:WASH CONTAMINATED CLOTHING BEFORE REUSE.

Exposure Controls

Respiratory Protection:NIOSH APPROVED DUST MASK
Ventilation:MECHANICAL PREFERRED
Protective Gloves:RUBBER
Eye Protection:CHEMICAL GOGGLES
Other Protective Equipment:RUBBER BOOTS & APRON; EMERGENCY SHOWER, EYE WASH
Supplemental Safety and Health
1345 TANEY, NORTH KANSAS CITY, MO 64116.

Chemical Properties

Solubility in Water:MODERATELY
Appearance and Odor:AMBER POWDER WITH NO ODOR.

Stability

Stability Indicator/Materials to Avoid:YES
STRONG ACIDS AND OXIDIZABLE MATERIALS
Hazardous Decomposition Products:NONE

Disposal

Waste Disposal Methods:DISPOSE OF ACCORDING TO FEDERAL, STATE AND LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.