ALLOY C263

MSDS Number

BBTYD

National Stock Number

9535-00F006116

Product Name

ALLOY C263

Manufacturer

G AND S TITANIUM INC

Product Identification

Product ID:ALLOY C263 MSDS Date: 01/01/1987 FSC:9535 NIIN:00F006116 MSDS Number: BBTYD

Responsible Party

G & S TITANIUM, INC/WOOSTER, OH 44691

Emergency Phone: (216) 263-0564

Cage: FO168

Contractor

G & S TITANIUM, INC/WOOSTER, OH 44691

WOOSTER, OH 44691

(216) 263-0564

Cage: FO168

Ingredients

CHROMIUM (SARA III)

CAS: 7440-47-3

RTECS: GB4200000

Fraction By Weight: 20%

OSHA PEL1 MG/M3

ACGIH TLV: 0.5 MG/M3; 9192 EPA Report Quantity: 1 LB DOT Report Quantity: 1 LB

COBALT (SARA III)

CAS: 7440-48-4 RTECS: GF8750000

Fraction By Weight: 20% OSHA PELO.1 MG/M3;AS CO

ACGIH TLV: 0.05 MG/M3; DUST 9293

MOLYBDENUM CAS: 7439-98-7



RTECS: QA4680000 Fraction By Weight: 6% OSHA PEL15 MG/M3 TDUST ACGIH TLV: 10 MG/M3; 9293

NICKEL (SARA III)
CAS: 7440-02-0
RTECS: QR5950000
Fraction By Weight: 51%

OSHA PEL1 MG/M3

ACGIH TLV: 1 MG/M3; 9192

TITANIUM DIOXIDE

CAS: 13463-67-7 RTECS: XR2275000

Fraction By Weight: 2 - 10% OSHA PEL15 MG/M3 TDUST

ACGIH TLV: 10 MG/M3 TDUST; 9293

Hazards

Effects of Overexposure: NAUSEA; TIGHTNESS OF CHEST; FEVER; EYES, NOSE, THROAT, OR SKIN IRRIT; LOSS OF CONSCIOUSNESS/DEATH.

First Aid

First Aid:INHALATION: REMOVE TO FRESH AIR. IF VICTIM IS UNCONSCIOUS, ADMINISTER OXYGEN. SKIN: BRUSH OFF SKIN/CLOTHING. WASH W/SOAP & WATER. WOUNDS: REMOVE METALLIC PARTICLES/CLEANSE. INGESTION: SEEK MED ATT. EY ES: FLUSH W/WATER. SEEK MED ATT.

Fire Fighting

Flash Point: NONFLAMMABLE

 ${\tt Extinguishing\ Media:SAND,\ DOLOMITE,\ GRAPHITE\ POWDER,\ OR\ SODIUM}$

CHLORIDE.

Unusual Fire/Explosion Hazard: MODERATE FIRE & EXPLOSIVE HAZARD WHEN EXPOSED TO HEAT, FLAME, ELECTRIC CURRENT, OR SPARK.

Accidental Release

Spill Release Procedures: RESIDUE FROM CUTTING OR GRINDING SHOULD BE SWEPT OR VACUUMED & PLACED IN SUITABLE COAINERS.

Handling

Handling and Storage Precautions: PREVENT ACCUMULATION OF DUST, GRINDINGS, ETC. THROUGH THE USE OF GOOD HOUSEKEEPING PRACTICES.

Exposure Controls

Respiratory Protection: IF TLVS ARE EXCEEDED, USE OSHA APPROVED

RESPIRATOR.

 $\label{thm:provide exhaust ventilation to keep Eye Protection: GOGGLES Other Protective Equipment: TO BE USED WHEN CUTTING, GRINDING, OR \\$

WELDING.

Supplemental Safety and Health

MSDS UNDATED

Chemical Properties

Solubility in Water: NOT SOLUBLE



Appearance and Odor: STEEL GRAY IN COLOR.

Stability

Stability Indicator/Materials to Avoid:YES STRONG OXIDIZING AGENTS, NITRIC OR CHROMIC ACIDS.

Disposal

Waste Disposal Methods: DISPOSAL BY LOCAL, STATE, OR FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.