https://msdsreport.com/msds/BCQLH

CAUSTIC SODA 50% RAYON GRADE

MSDS Number

BCQLH

National Stock Number

6810-00N008503

Product Name

CAUSTIC SODA 50% RAYON GRADE

Manufacturer

OLIN CORP

Product Identification

Product ID:CAUSTIC SODA 50% RAYON GRADE MSDS Date:01/01/1987 FSC:6810 NIIN:00N008503 MSDS Number: BCQLH

Responsible Party

OLIN CORPORATION

120 LONG RIDGE RD

STAMFORD, CT 06904

US

Cage: 0G578

Contractor

OLIN CORPORATION

STAMFORD, CT 06904-1355

US

203-356-3449

Cage: 0G578

Ingredients

SODIUM HYDROXIDE (SARA III)

CAS: 1310-73-2

RTECS: WB4900000

OSHA PEL2 MG/M3

ACGIH TLV: C 2 MG/M3; 9293

EPA Report Quantity: 1000 LBS

DOT Report Quantity: 1000 LBS

Hazards

Effects of Overexposure: CAUSES BURNS TO ALL TISSUES CONTACTED. BURNS FREQUENTLY RESULT IN DEEP ULCERATION.

First Aid

First Aid:EYES:FLUSH W/PLENTY OF H*20 FOR @ LEAST 15 MIN.CALL MD. SKIN:FLUSH W/H*20 FOR 15 MIN.CALL MD. INGEST:WASH OUT MOUTH W/H*20.DRINK LARGE QUANTITIES OF H/20.DO NOT INDUCE VOMITING.CALL MD. INHAL:REMOVE V ICTIM TO FRESH AIR,CALL MD.

Fire Fighting



Flash Point:N/A (MFR) Lower Limits:N/D Upper Limits:N/D Extinguishing Media:NON-COMBUSTIBLE-CHOOSE EXT MEDIA SUITABLE FOR SURROUND MATL. Fire Fighting Procedures:USE NIOHS/MSHA APPROVED SCBA WHERE MATL INVOLVED IN FIRE.

•

Accidental Release

Spill Release Procedures:WEAR NIOSH/MSHA APPROVED DUST/MIST RESPIRATOR.WEAR GOGGLES,COVERALLS & NEOPRENE,RUBBER,BUNA-N/BUTYL RUBBER GLOVES & BOOTS.ADD NON-REACTIVE DRY ABSORBENT(DIATOMACEOUS EARTH).SHOVEL/SWEEP UP & PLACE IN APPROVED DOT CONTAINER & SEAL. (SEE SUPP DATA)

Handling

Handling and Storage Precautions:AVOID EYE,SKIN/CLOTHING CONTACT.DONT INGEST.UPON CONTACT W/SKIN OR EYES,WASH OFF W/H*20.AVOID BREATHING MIST.STORE IN COOL,WELL-VENTILATED PLACE. Other Precautions:SEPARATE FROM ACIDS,METALS, & EXPLOSIVES.

Exposure Controls

Respiratory Protection:NIOSH/MSHA APPROVED RESPIRATOR APPROPRIATE FOR EXP OF CONCERN Ventilation:AS REQUIRED TO KEEP AIRBORNE CONCENTRATIONS BELOW TLV. Protective Gloves:NEOPRENE,RUBBER Eye Protection:CHEM WORKERS GOGGLES Other Protective Equipment:COVERALLS,IMPERVIOUS BOOTS,BUNA-N GLOVES,FACE SHIELD. Supplemental Safety and Health ND=NO DATA. STEPS TO BE TAKEN IF SPILLED:WASH ALL CONTAMINATED CLOTHING BEFORE REUSE.IF LARGE SPILL,CALL EMER TELEPHONE NUMBER 1-800-654-6911.BOILING PT:142-148C. DATE OF PREP;11-27-85.

Chemical Properties

Boiling Pt:B.P. Text:288-298F Vapor Pres:N/D Vapor Density:N/D Spec Gravity:N/D Evaporation Rate & Reference:NO DATA Solubility in Water:SOLUBLE Appearance and Odor:CLEAR COLORLESS SOLUTION, PH>12. Percent Volatiles by Volume:N/D

Stability

Stability Indicator/Materials to Avoid:YES ACIDS Stability Condition to Avoid:NONE KNOWN Hazardous Decomposition Products:NONE KNOWN

Disposal

Waste Disposal Methods:DISPOSE OF CONTAMINATED PRODUCT,EMPTY CONTAINERS & MATERIALS USED IN CLEANING UP SPILLS/LEAKS IN A MANNER APPROVED FOR THIS MATERIAL.CONSULT APPROPRIATE FEDERAL,STATE & LOCAL REGULATORY AGENCIES TO AS CERTAIN PROPER DISPOSAL PROCEDURES.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.