

MACUBLACK PRE-DIP

MSDS Number

BDBMT

National Stock Number

6850-00-141-2945

Product Name

MACUBLACK PRE-DIP

Manufacturer

MACDERMID INC

Product Identification

Product ID:MACUBLACK PRE-DIP MSDS Date:01/01/1985 FSC:6850 NIIN:00-141-2945 MSDS Number: BDBMT

Responsible Party

MACDERMID, INC.

50 BROOKSIDE RD

WATERBURY, CT 06720

US

Emergency Phone: NONE

Cage: KO215

Contractor

MACDERMID, INC.

MACDERMID, INC

671

WATERBURY, CT 06720

203-575-5700

US

Cage: KO215

Ingredients

SODIUM HYDROXIDE (SARA III)

CAS: 1310-73-2 RTECS: WB4900000

Fraction By Weight: 90%

OSHA PEL2 MG/M3

ACGIH TLV: C 2 MG/M3; 9293 EPA Report Quantity: 1000 LBS DOT Report Quantity: 1000 LBS

NON-HAZARDOUS COMPONENTS

Fraction By Weight: 10%

Hazards

Effects of Overexposure: IRRIT NOSE; PNEUMONTIS; BURNS EYES, SKIN; TEMPORARY



LOSS OF HAIR

First Aid

First Aid: EYES: FLUSH W/WATER FOR 15 MINUTES. CONTACT DR; SKIN-WASH W/WATER. FOLLOW WITH VINEGAR.; INTERNAL; GIVE PLENTY OF WATER. GET MEDICAL AID.

Fire Fighting

Fire Fighting Procedures: USE OF WATER ON MATERIAL GENERATES HI HEATS OF REACTION

Unusual Fire/Explosion Hazard: CONTAINS STRONG OXIDIZING AGENT WHICH CAN CAUSE COMBUSTION WHEN BROUGHT IN CONTACT WITH COMBUSTIBLES

Accidental Release

Spill Release Procedures:IMMED SWEEP UP SPILLED MATL & SHOVEL INTO CONTAINERS. RINSE/FLUSH AREA W/LG AMTS OF WATER. NEUTRALIZE RINSE WATER W/VINEGAR/DILUTE ACID.

Handling

Handling and Storage Precautions:STORE IN DRY AREA Other Precautions:IF MATERIAL IS SPILLED ON CLOTHING, WASH IMMEDIATELY W/ COLD WATER.

Exposure Controls

Respiratory Protection: DUST TYPE MASK

Ventilation: AS REQUIRED TO MAINTAIN AIR LEVEL BELOW TLV; MECHANICAL

Protective Gloves: RUBBER Eye Protection: FACE SHIELD

Other Protective Equipment: RUBBER APRON & BOOTS.

Supplemental Safety and Health

THIS ITEM IS PART B OF A MULTICOMPONENT KIT.

Chemical Properties

HCC:B1

Spec Gravity: 2.13

Solubility in Water: COMPLETE

Appearance and Odor: WHITE GRANULAR POWDER, ODORLESS

Stability

Stability Indicator/Materials to Avoid:YES ACIDS, OXIDIZABLE MATERIALS,FLAMMABLES. Stability Condition to Avoid:SOURCES OF MOISTURE Hazardous Decomposition Products:NO

Disposal

Waste Disposal Methods: NEUTRALIZE WITH SUITABLE AGENT.DISCARD IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.