msds report

https://msdsreport.com/msds/BDPTW

<u>1B53</u>

MSDS Number

BDPTW

National Stock Number

5960-00-262-0192

Product Name

1B53

Manufacturer VARIAN ASSOCIATES BEVERLY DIV

Product Identification

Product ID:1853 MSDS Date:01/01/1985 FSC:5960 NIIN:00-262-0192 MSDS Number: BDPTW

Responsible Party

VARIAN ASSOCIATES, BEVERLY DIV

8 SALEM ROAD

BEVERLY , MA 01915-1018

US

Emergency Phone: 508-922-6000 EXT.285

Info Phone: 506-922-6000 EXT.285

Cage: 88236

Contractor

COMMUNICATIONS AND POWER INDUSTRIES INC

BEVERLY, MA 01915-5595

US

978-922-6000 EXT.285

Cage: 88236

Ingredients

COBALT (SARA III)

CAS: 7440-48-4

RTECS: GF8750000

OSHA PEL0.1 MG/M3;AS CO

ACGIH TLV: 0.05 MG/M3;DUST 9293

Hazards

Effects of Overexposure:HAZ DEGREE DEPENDS ON TYPE/QUANT OF RADIATION. LATENT EFFECTS:SOMATIC/GENETIC DAMAGE.

First Aid

First Aid:USE FIRST AID. CALL MEDICAL EMERGENCY CARE. REMOVE/ISOLATE COMTAMINATED CLOTHING.SHOWER VICTIM(S) W. SOAP & H*20. DETAIN PERSONNEL/EQUIPMENT EXPOSED. ADVISE MEDICAL PERSONNEL THAT VICTIM(S) MAY BE CON TAMINATED.

Fire Fighting



Extinguishing Media: EXTINQUISH W. AGENT SUITABLE FOR SURROUNDING FIRE. Fire Fighting Procedures: WEAR CHEMICAL PROTECTIVE SUIT WITH SELF CONTD BRTHG APP.

Unusual Fire/Explosion Hazard:SOME OF MATL MAY BURN. CONT MAY EXPLODE IN HEAT OF FIRE.

•

Accidental Release

Spill Release Procedures: HANDLE BROKEN DEVICE WITH GLOVES AND FORCEPS.

Handling

Handling and Storage Precautions: SHIELD ACCORDING TO EMITTED RADIATION. PROTECT FROM FILM/FILM PLATES. KEEP CONTAINERS CLOSED. STORE IN AREA FOR RADIOACTIVE MATERIALS.

Exposure Controls

Respiratory Protection:SCBA IF INVOLVED IN FIRE, OTHERWISE GAS MASK. Ventilation:PROVIDE MECHAN(GEN/LOCAL EXHAUST)VENT TO MAINTN Protective Gloves:IMPERVIOUS Eye Protection:SAFETY GLASSES Other Protective Equipment:EYE WASH STATION. APRONS. SPECIAL IMPERVIOUS CLOTHING. Supplemental Safety and Health SOURCE OF DATA-MIL HANDBOOK 600-1 SEP 76.SAFETY & HEALTH DATA DEVELOPED BY DGSC-STF.

Chemical Properties

HCC:A2

Stability

Stability Indicator/Materials to Avoid:YES ISOLATE,SEGREGATE FROM MOST OTHER TYPE MATERIAL Hazardous Decomposition Products:DEPENDS ON CHEMICAL COMPOSITION; FISSION PRODUCTS

Disposal

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-IN ACCORDANCE WIH DOD REGULATIONS AND FEDERAL,STATE & LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.