

GEON 8815

MSDS Number

BFDNY

National Stock Number

8040-00-543-4312

Product Name

GEON 8815

Manufacturer

B F GOODRICH CO CHEM GROUP

Product Identification

Product ID:GEON 8815
MSDS Date:01/01/1987
FSC:8040
NIIN:00-543-4312
MSDS Number: BFDNY

Responsible Party

B F GOODRICH CO, CHEM GROUP
Emergency Phone: 216-447-6000
Cage: GO874

Contractor

BF GOODRICH CHEMICAL GROUP
CLEVELAND, OH 44131-2508
US
216-447-6000
Cage: 91427

Ingredients

POLY(VINYL CHLORIDE)
RTECS: KV0350000

VINYL CHLORIDE (SARA III)

CAS: 75-01-4

RTECS: KU9625000

OSHA PELSEE 1910.1017

ACGIH TLV: 5 PPM, A1; 9293

EPA Report Quantity: 1 LB

DOT Report Quantity: 1 LB

HEAVY METAL STABILIZERS, BARIUM CADMIUM ZINC STABILIZER

MONOMERIC, POLYMERIC OR MIXED ESTER PLASTICIZER IN FLEXIBLE

PIGMENTS BASED ON LEAD, CHROMIUM, MERCADMIUMS, IRON OXIDES

Hazards

Effects of Overexposure:EYE/NOSE/THROAT IRRIT. ASTHMATICS & INDIVS W/OTHER CHRNC OBSTRCTV RESP DISEASES MAY DEVLV BRONCHSPSM

First Aid

First Aid:INH: MOVE TO FRESH AIR, CALL MD. EYE: IMMED FLUSH W/WATER AT LEAST 15 MIN. CALL MD.

Fire Fighting

Extinguishing Media:WATER, ABC DRY POWDER, PROTEIN-TYPE AIR FOAM

Fire Fighting Procedures:CO*2 INEFFECTIVE. WEAR SELF-CNTND BRTHNG APPARATUS.

Unusual Fire/Explosion Hazard:DUST HAS EXPLOSIVE POTENTIAL. CONTROL OR ELIMINATE LIKELY IGNITION SOURCES. VENT WELL.

Accidental Release

Spill Release Procedures:SWEEP, SHOVEL OR VACUUM INTO CNTNRS FOR REUSE OR DISPOSAL. IF DUST POSS, USE PROPER RESP PROT.

Handling

Handling and Storage Precautions:USE UNDER WELL-VENT CONDITIONS. AVOID BRTHNG FUMES. WASH HANDS THOROUGHLY AFTER HANDLING. COOL REGRIND BEFORE PLACING IN CNTNRS.

Exposure Controls

Respiratory Protection:IF DUST POSSIBLE, WEAR NIOSH/MSHA APPRVD RESP PROT

Ventilation:LOCAL EXH, PROVIDE ADEQUATE VENT

Protective Gloves:RUBBER GLOVES

Eye Protection:SAFETY GLASSES

Supplemental Safety and Health

PROD HAS SLIGHT ODOR

Chemical Properties

HCC:N1

Spec Gravity:1.34

Solubility in Water:SLIGHT

Appearance and Odor:PIGMENTED OR UNPIGMNTD CUBICAL GRANULES OR POWDER

Stability

Stability Indicator/Materials to Avoid:YES

ACETAL OR ACETAL COPOLYMERS, AMINE CONTAINING MATLS

Hazardous Decomposition Products:CO, CO*2, HCL, SM AMTS AROMATIC & ALIPHATIC HYDROCRBNS

Disposal

Waste Disposal Methods:SANITARY LANDFILL OR INCINERATION IAW LOCAL, STATE, FED REG. MFR STATES NOT HAZ FOR WASTE DISPOSAL PER FED REG, 40 CFR 261.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.