

HUMISEAL 2A53, PART A

MSDS Number

BGNMT

National Stock Number

5970-01-136-7100

Product Name

HUMISEAL 2A53, PART A

Manufacturer

HUMISEAL DIV COLUMBIA CHASE CORP

Product Identification

Product ID:HUMISEAL 2A53, PART A

MSDS Date:01/01/1987

FSC:5970

NIIN:01-136-7100

MSDS Number: BGNMT

Responsible Party

HUMISEAL DIVISION,COLUMBIA CHASE CORP.

26-60 BROOKLYN QUEENS EXPRESSWAY WEST

WOODSIDE , NY 11377-0445

US

Emergency Phone: 718-932-0800

Info Phone: 718-932-0800

Cage: HUMIS

Contractor

HUMISEAL DIVISION/CHASE CORPORATION

WOODSIDE, NY 11377

US

718-932-0800

Cage: 99109

Ingredients

TOLUENE (SARA III)

CAS: 108-88-3

RTECS: XS5250000

Fraction By Weight: 20%.

OSHA PEL200 PPM/150 STEL

ACGIH TLV: 50 PPM; 9293

EPA Report Quantity: 1000 LBS

DOT Report Quantity: 1000 LBS

METHYL ISOBUTYL KETONE (SARA III)

CAS: 108-10-1

RTECS: SA9275000

Fraction By Weight: 13%.

OSHA PEL100 PPM/75 STEL

ACGIH TLV: 50 PPM/75 STEL; 9293

EPA Report Quantity: 5000 LBS

DOT Report Quantity: 5000 LBS

Hazards

Effects of

Overexposure:EYE,SKN:IRRIT,DEFAT,DERM.INHL:IRRIT,HEAD,NAUSEA,NOSEBLEED,
ANOREXIA.INGEST:POSS ORGAN ABNORMALITY OR DAM

First Aid

First Aid:INHAL:RMV TO FRESH AIR. IF NOT BRTHNG GIVE CPR; IF BRTHNG
DIFF GIVE OXYGEN. EYE:IMMED FLUSH W/PLENTY OF WATER. SKIN:WASH
W/SOAP & WATER. RMV CONTAM CLTHG & SHOES. INGEST:DO NOT INDUCE
VOMIT. NOTHG BY MOUTH IF UNCONSC. GET MEDICAL ATTN.

Fire Fighting

Flash Point:50F/10C TCC

Lower Limits:1.2

Upper Limits:7.5

Extinguishing Media:FOAM,CO*2,DRY CHEMICAL

Fire Fighting Procedures:FLAM LIQ FIRE.USE SCBA PP MODE.COOL EXP CONTR
W/WATER SPRAY

Unusual Fire/Explosion Hazard:FLAMMABLE VAPOR IS HEAVIER THAN AIR, MAY
TRAVEL TO IGNITION SOURCE AND FLASHBACK. AVOID XS HEAT,ETC.

Accidental Release

Spill Release Procedures:VENTILATE AREA & EVACUATE. REMOVE HEAT &
IGNITION SOURCES. COLLECT SPILL W/ABSORBENT OR NON-SPARKING SCOOP,
PLACE IN CLOSED CONTAINER.

Handling

Handling and Storage Precautions:FLAMMABLE LIQUID:AVOID
HEAT,SPARKS,OPEN FLAME. GROUND CONTAINERS & LIMIT FREE FALL WHEN
POURING. PLACE CONTAMINATED RAGS IN WATER.

Other Precautions:AVOID EYE/SKN CONTACT. AVOID INHL VAPORS. EMPTY
CONTAINERS MAY CONTAIN FLAMMABLE VAPORS. DO NOT PUNCTURE, WELD, OR
CUT ON OR NEAR CONTAINERS.

Exposure Controls

Respiratory Protection:USE CCROV RESP OR SCBA AS REQD.

Ventilation:LOCAL EXH PREFERRED AT 60 FPM.

Protective Gloves:NEOPRENE

Eye Protection:CHEMICAL GOGGLES

Other Protective Equipment:EYEWASH FOUNTAIN, SHOWER.

Supplemental Safety and Health

MSDS DTD 30 JUL 85. PART A OF A TWO-PART KIT. KIT IS PEC TYPE "R".

KEY1:J1.

Chemical Properties

HCC:F2

Boiling Pt:B.P. Text:235F/113C

Vapor Pres:22.

Vapor Density:4.

Spec Gravity:1.07

Evaporation Rate & Reference:2.85 (BUAC=1)

Solubility in Water:NEG

Appearance and Odor:PALE YELLOW LIQUID, AROMATIC ODOR

Percent Volatiles by Volume:35.

Stability

Stability Indicator/Materials to Avoid:YES

OXIDIZERS

Stability Condition to Avoid:EXCESS HEAT,IGNITION SOURCES.

Hazardous Decomposition Products: CARBON OXIDES

Disposal

Waste Disposal Methods: INCINERATE IAW ALL LAWS & REGS.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.