

RX MIDACAST

MSDS Number

BJCRR

National Stock Number

6520-01-087-8564

Product Name

RX MIDACAST

Manufacturer

JENERIC INDUSTRIES INC

Product Identification

Product ID:RX MIDACAST MSDS Date:01/01/1987 FSC:6520 NIIN:01-087-8564

NIIN:01-087-8564 MSDS Number: BJCRR

Responsible Party

JENERIC INDUSTRIES, INC.

125 NORTH PLAINS INDUSTRIAL RD.

WALLINGFORD, CT 06492

Emergency Phone: (203) 265-7397

Info Phone: (203) 265-7397

Cage: 58796

Contractor

JENERIC INDUSTRIES INC

WALLINGFORD, CT 06492-5841

(203) 265-7397 Cage: 58796

Ingredients

GOLD

CAS: 7400-57-5 RTECS: MD5070000

Fraction By Weight: 26-63%

PALLADIUM

CAS: 7440-05-3

Fraction By Weight: 3-10%

SILVER (SARA III)

CAS: 7440-22-4

RTECS: VW3500000

Fraction By Weight: 0-39% OSHA PEL0.01 MG/M3

ACGIH TLV: 0.1 MG/M3; 9192



EPA Report Quantity: 1 LB DOT Report Quantity: 1 LB

COPPER (SARA III) CAS: 7440-50-8

RTECS: GL5325000

For the Dec Weight 7 F

Fraction By Weight: 7.5-20%

OSHA PEL0.1MG/M3 FUME/1 DUST ACGIH TLV: 0.2MG/M3 FUME; 9192 EPA Report Quantity: 5000 LBS DOT Report Quantity: 5000 LBS

CAS: 7440-66-6

RTECS: ZG8600000

Fraction By Weight: 0-1%

ZINC (SARA III)

OSHA PEL10 MG ZNO/M3

ACGIH TLV: 10 MG ZNO/M3; 9192 EPA Report Quantity: 1000 LBS DOT Report Quantity: 1000 LBS

IRIDIUM

Fraction By Weight:

INDIUM

CAS: 7440-74-6 RTECS: NL1050000 Fraction By Weight: OSHA PEL0.1 MG/M3

ACGIH TLV: 0.1 MG/M3; 9192

Hazards

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:SKIN: DERMATITIS. INHALATION:

IRRITATION OF THE UPPER RESPIRATORY TRACT.

Explanation of Carcinogenicity: NONE

Effects of Overexposure: SKIN: DERMATITIS. INHALATION: IRRITATION OF THE

UPPER RESPIRATORY TRACT.

Medical Cond Aggravated by Exposure: DERMATITIS

First Aid

First Aid: EYE: FLUSH THOROUGHLY W/RUNNING WATER, EVEN UNDER EYELID. SKIN: FLUSH & SCRUB THOROUGHLY W/SOAP & WATER. INHALATION: REMOVE PERSON TO FRESH AIR, ASSIST BREATHING W/ADDITIONAL OXYGEN IF NECESSARY. INGE STION: GIVE LARGE QUANTITIES OF WATER TO INDUCE VOMITING. CONTACT PHYSICIAN.

Fire Fighting

Unusual Fire/Explosion Hazard: THE ALLOYS ARE FIRE & EXPLOSION



RESISTANT.

Accidental Release

Spill Release Procedures: REMOVE DUST BY VACUUMING OR WET SWEEPING TO PREVENT POWDERING IN THE AIR. WHENEVER POSSIBLE, RECOVER DUST BECAUSE IT HAS ECONOMIC VALUE.

Handling

Handling and Storage Precautions: AVOID CONTACT W/SKIN. GRIND & POLISH W/ADEQUATE VENTILATION ONLY.

Exposure Controls

Respiratory Protection: WEAR APPROVED RESPIRATORS.

Ventilation: MECHANICAL/LOCAL EXHAUST VENTILATION: FILTRATION SHOULD BE

EMPLOYED.

Eye Protection: GOGGLES

Other Protective Equipment: COVERALLS, PROTECTIVE CLOTHING

Supplemental Safety and Health

SILVER & COPPER ARE PRESENT IN ALL THESE ALLOYS IN SMALL AMOUNTS (39%

OR LESS).

Chemical Properties

Melt/Freeze Pt:M.P/F.P Text: 1570-1687F

Spec Gravity: 13.18

Solubility in Water: INSOLUBLE

Appearance and Odor: GOLDEN COLOR, NO ODOR

Stability

Stability Indicator/Materials to Avoid:YES Stability Condition to Avoid:HIGH TEMPERATURES Hazardous Decomposition Products:FUMES

Disposal

Waste Disposal Methods: NO SPECIAL PRECAUTIONS ARE REQUIRED FOR BULK (SOLID) SHAPES, SUCH AS INGOTS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.