

https://msdsreport.com/msds/BYDFM

0230 HIV-1/HIV-2 EIA KIT PLATE SEALERS

MSDS Number

BYDFM

National Stock Number

6550-01-358-0777

Product Name

0230 HIV-1/HIV-2 EIA KIT PLATE SEALERS

Manufacturer

GENETIC SYSTEMS CORP

Product Identification

Product ID:0230 HIV-1/HIV-2 EIA KIT PLATE SEALERS MSDS Date:01/04/1993 FSC:6550 NIIN:01-358-0777 Kit Part:Y MSDS Number: BYDFM

Responsible Party

GENETIC SYSTEMS CORP

6565 185TH AVE NE

REDMOND, WA 98052

US

Emergency Phone: 206-881-8300

Info Phone: 206-881-8300

Cage: 0D6X2

Contractor

GENETIC SYSTEMS CORP

REDMOND, WA 98052

US

206-881-8300

Cage: 0D6X2

Ingredients

MANUFACTURER LISTS NOTHING UNDER "INGREDIENTS" IMPLYING

RTECS: 9999999ZZ

Fraction By Weight: 100%

Fire Fighting

Extinguishing Media:USE MEDIA APPROPRIATE FOR SURROUNDING FIRE. Fire Fighting Procedures:NONE.

Exposure Controls

Supplemental Safety and Health

Chemical Properties

HCC:V4 Appearance and Odor:VARIABLE, DEPENDING ON COMPONENT.

Stability

Stability Indicator/Materials to Avoid:YES



_ _ _ _ _ _ _ _ _ _ _ _

NONE SPECIFIED BY MANUFACTURER.

Stability Condition to Avoid:NONE KNOWN WHEN USED AS INTENDED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.